



Countries:	AUSTRALIA, CANADA, TAIWAN, UNITED STATES, MEXICO, PUERTO RICO, GUAM, KOREA, SOUTH KOREA, NEW ZEALAND	Document ID:	IK1201113
Availability:	ISIS, FleetISIS	Revision:	14
Major System:	ENGINES	Created:	4/3/2014
Current Language:	English	Last Modified:	2/26/2016
Other Languages:	Español	Author:	Ben Krejcie
Viewed:	20397		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		View My Bookmarks				70	10

Title: 2010 MaxxForce 11 & 13 and 2013 N13 HT EGR Core Removal/Installation

Applies To: 2010 MaxxForce11/13, 2013 N13, All Truck Models

CHANGE LOG

2016/02/26 - Added note for oil change on HT Core Service
 2015/11/02 - Revised (confusing) wording in description, regarding core vs. full cooler (feedback).
 2015/09/16 - Removed link to IK1201100 as it has been retired and the content integrated into the Diagnostic manuals.
 2015/09/14 - Fixed link for LT Core Replacement Diagnostics and 111-1 FCAP.
 2015/07/28 - Fixed links to Fault Codes, put lambda relearn into repair steps,
 2014/10/02 - Revised note about not using impact on tool, added note about DOC coolant contamination (end of repair procedure--never bake), added another note in diagnostics section, about half cooler replacement being necessary in some cases, added comment about damaged core during shipping in parts section, and revised comment about tightening down the support rods, in "Removal" section.
 2014/09/12 - Revised instructions on vacuum filling. Minor grammar changes. Removed Notice for mis-built kits (all should be fixed now)
 2014/07/22 - Added link/instructions to repair video in LMS ("Repair Procedure")

DESCRIPTION

A faster, more effective procedure for High Temp (HT) Exhaust Gas Recirculation (EGR) Cooler repair has been developed. This document will guide the user through the procedure of in chassis replacement of the cooler core for a 2010 Emissions MaxxForce 11 or 13 or 2013 Emissions N13. The new procedure must be followed in lieu of HT cooler assembly replacement for **INTERNAL** leaks.

Please note, if the LT is being repaired with a High Temp (HT) replacement, reference Master Service Information site ([2659-21 FCAP](#)) for LT core replacement instructions.

It is important to thoroughly review the following instructions to prevent tool damage. A lot has been learned through the development of the tool, and important notes/areas of concern are specifically called out at relevant points (ex; never use an impact to remove/install the core).

SYMPTOMS

Diagnostic Trouble Codes & Dashboard Indicator Lights:

DTC/Light	Description
SPN 111 FMI 1	Low Coolant
SPN 2659 FMI 21	EGR Low Flow

Customer Observations or Concerns:

- Malfunction Indicator Light (MIL)
- Red Stop Lamp (RSL)
- Coolant consumption
- Low coolant
- Coolant puddling under engine

- White smoke from the exhaust
- Coolant in the oil or oil analysis

SPECIAL TOOLS

Tool Description	Tool Number	Comments	Instructions
LT Core Replacement Tool	12-892-04		Link
HT Core Replacement Tool	12-892-05		Link
Coolant Management Tool	KL5007NAV		Link
EGR Leak Detection Kit	12-892-02		Link

DIAGNOSTIC STEPS


All diagnostic steps should be completed through the [Fault Code Action Plans](#) for [111-1](#) or [Coolant Consumption/Loss](#). At this point, the truck should have been diagnosed with an internal leak of the HT cooler.

REPAIR NOTES:

- The following procedure should **NOT BE USED** if the cooler is **LEAKING EXTERNALLY** for cracks, porosity, broken fittings, etc. Instead, replace the entire HT cooler assembly.
- If the cooler is leaking at the joint between the HT and the center plate, replace the HT assembly.
- If leaking between the center plate and the LT assembly, reference the LT seal kit in the parts section.
- If leaking from the LT Y-Fitting (only if the fitting is bolt-on), reference the LT Y-Fitting kit.
- If the HT module and mid-plate are "**mis-aligned**" from the factory, please reference [TSI 13-12-18](#) for resolution.
- An oil and filter change must be performed after all HT core service.**
- The core R&R procedure is NOT 100% effective. There will be instances when the core is caught during removal, stuck during install, etc, where the half cooler will have to be replaced.** For questions or concerns on this, please open a (Big Bore) Tech Services case file.

TESTING NOTE

If **BOTH** cooler halves are found leaking, make sure the LT cooler did not appear failed due to residual air in the core from the High Temp testing. Typically this happens when the leak detection hose is not vented to atmosphere (left in water) between tests and/or when the HT is tested and the fittings are switched quickly--the air pressure in the core passages is still enough to cause bubbles when putting pressure to the LT.






Figure 1: 2010 MaxxForce 11/13 EGR Cooler Assembly

Item 1: High Temp (HT) Cooler

Item 2: Low Temp (LT) Cooler

Item 3: LT Cooler Pressure Test Port (dearation fitting)

Item 4: HT Cooler Pressure Test Port (dearation fitting)

Visual inspection should never be used for diagnosing a bad cooler. The cooler (especially when constantly operated cold--read, moving the truck around the lot) will cause condensation build-up, and when mixed with soot/exhaust constituents, can be easily confused with coolant. ALWAYS pressure test the cooler.

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity Required	Notes
Kit, High Temp Core	2513445C91	1	Required
Kit, Low Temp Core	2513209C91	1	ONLY if necessary
Module, HT	3014254C95	1	ONLY if necessary
Module, LT (MaxxForce)	3015862C92	1	For external leaks ONLY, in place of LT Kit
Module, LT (N13)	2511089C91	1	For external leaks ONLY, in place of LT Kit
Kit, Low Temp Seal	2512193C91	1	For external leaks between the LT and the plate

Kit, Y-Fitting (Low Temp)	1844447C1		For leaks at LT Y-Fitting (bolt-on ONLY)
P-80 Assembly Lube	2511097C1	1	Case of 6 Pints

NOTE

If the **core is damaged** during shipping (ie, bent header plate), **DO NOT USE** it. The packaging is being revised to better withstand the poor shipping handling. Any stresses on the braze/header will cause an exponential decrease in the core's strength.

REPAIR STEPS

REPAIR VIDEO

The entire repair procedure has been put into video and available in the Learning Management System. [Go to the LMS via this link](#). Then "Course Catalog," "Critical Repair Videos," "HT EGR Cooler Core Replacement Procedure," and enroll. After enrolling, go back to "My Current Enrollments" to watch. If you do not see the same link in the course catalog, do a search (Ctrl "F") and search for "HT EGR Cooler Core Replacement Procedure."

The following repair steps are for the cooler removal and installation in chassis.

WARNING

To prevent personal injury or death, read all safety instructions in the "Safety Information" section of the diagnostic manual, [linked here](#).

WARNING

To prevent personal injury or death, shift transmission to park or neutral, set parking brake, and block wheels before doing diagnostic or service procedures.

WARNING

To prevent personal injury or death, make sure the engine has cooled before removing components.


WARNING

To prevent personal injury or death, do not let engine fluids stay on your skin. Clean skin and nails using hand cleaner and wash with soap and water. Wash or discard clothing and rags contaminated with engine fluids.

REMOVAL PROCEDURE:

The dog house, coolant crossover and EGR tubes should have already been removed to gain access to the cooler for pressure testing.

1. Remove and discard the 9 bolts securing the EGR Valve to the HT cooler housing.
2. Remove the two dowel pins in the top right and bottom left corner of the housing.
3. Discard the EGR valve to cooler gasket.
4. Install the removal tool






Figure 2: HT Core Removal Tool

Item 1: Removal plate
 Item 2: Support rods
 Item 3: Forcing screw
 Item 4: Thumb screws

a. Screw in the support rods in the two upper right, and lower, bottom left corner, holes (**Figure 2**, Item 2). **Tighten using a 9mm open-end wrench.**

CAUTION

It is critical that the rods get torqued to the housing. There is a bevel between the threads and the shaft, designed specifically to drive the cooler header onto the shaft. **There is a distinct difference between bottoming out on the header plate, and bottoming out in the housing (hard stop).** Failure to do so will lead to the header being caught on the rod and breaking/bending the rod. There have been instances of the housing being damaged to the point of replacement, as well.

b. Slide the puller over the rods

c. Attach/tighten the thumb screws (**Figure 2**, Item 4).



Figure 3: HT Core Tool Plate with Screws

d. Lastly screw the removal plate into the core using the eight screws supplied in the HT kit (Figure 3).

Reference the HT Tool Instructions ([12-892-5, TL2900093](#)) for more information.




Figure 4: High Temp Core and Spring Clips

Item 1: HT Cooler Core

Item 2: Spring Clips

5. Back out the bolt to extract the core from the housing (**counter-clockwise**).

Notes:

-There are two pairs of spring clips supporting the core in the housing. Therefore, the core will need to be pulled about 16 inches before it will be free to remove.

-NEVER use an impact on the tool. The tool was not designed to handle the stresses because core and/or housing damage will result from the uncontrolled force. Always use a ratchet.

6. Unscrew the knobs from the rods.
7. Remove the cooler core from the housing.
8. Unscrew the screws from the removal plate/core and discard.
9. Unscrew the rods to remove the gasket (discard).





Figure 5: HT Diffuser O-Rings

Item 1: HT Housing
Item 2: Manifold (joint) Plate
Item 3: O-Rings

10. Use a pick to remove the four o-rings in the center of the cooler and discard. *The o-rings must be replaced every time the core is replaced. Non-compliance will result in premature failure of the core.*

INSTALLATION PROCEDURE:







Figure 6: HT Diffuser O-Rings

Item 1: HT Housing
Item 2: Manifold (joint) Plate
Item 3: O-Rings

1. Install the four o-rings from the HT kit (**Figure 6**, Item 3) and ensure they are seated properly.

NOTE

Make sure there is no debris in the o-ring grooves prior to installing the o-rings (they don't need to be spotless, just no soot chunks that will push the o-ring out of round). In development, this was the only instance of damaged o-rings (core outlet manifold cut off a section of the o-ring), outside of not actually seating them.



CAUTION

There are two o-ring designs and both are the same size with different durometers. Make sure to use only the black o-rings on the HT core and pink o-rings on the LT core.

2. Apply generous amounts of P-80 to the four o-rings.
3. Install the two dowel pins into the housing. Use a hammer to tap them in, if necessary.
4. Install the core to housing gasket (**Figure 8**, Item 1).
5. Screw in the four rods from the tool kit (tighten using a 9mm open-end wrench).




Figure 8: HT Core Installation

Item 1: Core to Housing Gasket
 Item 2: Installation Plate
 Item 3: Removal Plate
 Item 4: Dowel Pin

6. Apply liberal amounts of P-80 to the outlet manifold and spring clips of the HT core.
7. Slide the HT Core into the housing.
8. Attach the insertion plate to the tool and slide it over the rods.
9. Screw the thumbscrews onto the rods.
10. Use a torque wrench to tighten the bolt, which will drive the core into the housing. Stop when the core header touches the gasket.

NOTE

DO NOT OVER TIGHTEN. Stop when the plate merely touches the gasket/housing. The core should take up to 10 lb-ft of bolt torque to slide in. **Damage to the tubes will occur if the torque exceeds 15 lb-ft (equates to 1000 lb force).**

NEVER USE AN IMPACT. Failure to do so will lead to damage to the tool, core and housing.

NOTE

If the previous core and new core are on the opposite ends of the position spec, it's possible the plate will not line up and will cause the core to bottom out (on the plate, before sliding into the O-rings). The core/housing can be saved by loosening the HT/LT joint bolts (would require removing the cooler from the engine). This won't save time but will save a good core from being scrapped.

11. Remove the knobs, tool and rods.
12. Install the EGR Valve gasket.




Figure 9: EGR Valve Bolt Notation

13. Install the EGR valve and torque as follows, referencing Figure 9 for bolt position notation.
 - a. Hand tighten all
 - b. Torque "1-5-7-4" to 5 N-m (4 lb-ft)
 - c. Torque "5-1-6-2-7-3-4-8-9" to 24 N-m (18 lb-ft)
14. Attach all coolant lines for cooling system refill. Do not begin truck reassembly yet.
15. Vacuum fill the cooling system--if the system is unable to maintain vacuum, perform a cooling system pressure decay test. If no external leaks can be found, pressure test the EGR Cooler.

NOTE

The vacuum fill is a critical aspect of the repair. Any issues (cut/damaged/missing o-rings) will be caught here, as well as ensuring no air pockets are left in the system (which can reduce the life of the cooler or make the system appear leaking as the pockets are burped).

Bucket fill should never be performed. Any air pockets in the cooling system (especially the EGR Cooler) will result in thermal fatigue and significant reduction in the life of the core.

16. Reassemble all components removed for repair.
17. If cooler was replaced for internal leaking, follow Lambda sensor diagnostics to perform relearn and verify part integrity.

[2010-2013 MaxxForce 11](#)
[2010-2013 MaxxForce 13](#)
[2013-2014 N13](#)

18. Per best practice, verify repair.

Diesel Oxidation Catalyst Baking

A DOC should never be baked for coolant contamination. Baking will lead to the silicates (in the coolant) crystallizing over the substrate (not cleanable) and causing severe reduction in the efficiency of the DOC--ultimately requiring replacement. At this time, Navistar does not recommend visual inspection of DOC for coolant contamination, as there are many factors that play into DOC contamination and efficiency.

WARRANTY INFORMATION**Warranty Claim Coding:**

Group:	12000 - Engine
Noun:	892 - Cooler, EGR

Standard Repair Times:

Step	Description	SRT	Hours
HT CORE REPLACEMENT IN CHASSIS (see Example 1 below)			
	HT core replacement (not including press test) - ProStar	R12-8892U	3.4
	HT core replacement (not including press test) - TranStar	Q12-8892U	3.1
	HT core replacement (not including press test) - WorkStar	N12-8892U	3.1
	HT core replacement (not including press test) - CAT CT660	TC12-8892U	3.1
	HT core replacement (not including press test) - PayStar	T12-8892U	3.1
	HT core replacement (not including press test) - LoneStar	S12-8892U	3.4
EGR COOLER PRESSURE TEST			
	ProStar+ EGR Cooler Pressure Test (in-chassis)	R12-8892U-1	1.3
	TranStar EGR Cooler Pressure Test (in-chassis)	Q12-8892U-1	1.3
	WorkStar EGR Cooler Pressure Test (in-chassis)	N12-8892U-1	1.3
	CAT CT660 EGR Cooler Pressure Test (in-chassis)	TC12-8892U-1	1.3
LT CORE R&R IN CHASSIS WITH HT (see LT iKNow when LT ONLY rep'd)			
	ProStar+122 LT Core Replacement in Chassis	R12-8892U-3	1.3
	ProStar+113 LT Core Replacement in Chassis	R12-8892U-2	1.2
	TranStar LT Core Replacement in Chassis	Q12-8892U-2	1.6
	WorkStar LT Core Replacement in Chassis	N12-8892U-2	1.7
	CAT CT660 LT Core Replacement in Chassis	TC12-8892U-2	1.7
MODULE ASSEMBLY REMOVAL (see Example 2 Below)			
	ProStar+ Full Cooler Removal and Install	R12-6892U-20	5.8
	TranStar Full Cooler Removal and Install	Q12-6892U-20	5.6
	WorkStar Full Cooler Removal and Install	N12-6892U-20	6.1
	PayStar Full Cooler Removal and Install	T12-6892U-20	5.6
	LoneStar Full Cooler Removal and Install	S12-6892U-20	5.8
	CAT CT660 Full Cooler Removal and Install	TC12-6892U	6.4
HT or LT MODULE SEPARATION AND ASSEMBLY			
	ProStar+ Cooler Half R&R	R12-6892U-3	0.5

	TranStar Cooler Half R&R	Q12-6892U-3	0.5
	WorkStar Cooler Half R&R	N12-6892U-3	0.5
	PayStar Cooler Half R&R	T12-6892U-3	0.5
	LoneStar Cooler Half R&R	S12-6892U-3	0.5
	CAT CT660 Cooler Half R&R	TC12-6892U-3	0.5
EGR COOLER PRESSURE TEST (add-on when full/half cooler replaced)			
	ProStar+ In-Chassis Pressure test add-on	R12-6892U-1	0.8
	TranStar In-Chassis Pressure test add-on	Q12-6892U-1	0.8
	WorkStar In-Chassis Pressure test add-on	N12-6892U-1	0.8
	PayStar In-Chassis Pressure test add-on	T12-6892U-1	0.8
	LoneStar In-Chassis Pressure test add-on	S12-6892U-1	0.8
	CAT In-Chassis Pressure test add-on	TC12-6892U-1	0.8
LT CORE R&R OFF CHASSIS (add-on when HT MODULE replaced)			
	ProStar+122 LT Core Replacement off Chassis	R12-6892U-6	0.3
	ProStar+113 LT Core Replacement off Chassis	R12-6892U-6	0.3
	TranStar LT Core Replacement off Chassis	Q12-6892U-6	0.3
	WorkStar LT Core Replacement off Chassis	N12-6892U-6	0.3
	CAT CT660 LT Core Replacement off Chassis	TC12-6892U-6	0.3
MISCELLANEOUS RELEVANT SRTs			
	Engine Oil Replacement	A12-1889U	0.6
	Lambda Relearn or Replacement (see SRT section of 724-20 FCAP)		

EXAMPLE 1: A ProStar+113 has the HT **core** replaced for leaking and the LT core for 2659-21--the warranty claim should be:

EGR Cooler pressure test (R12-8892U-1, 1.3hrs)

HT Core R&R (R12-8892U, 3.4 hrs)

LT Core R&R (R12-8892U-2, 1.2 hrs)

Oil Change (A12-1889U, 0.6 hrs)

Lambda relearn/replacement (depends on the condition of the Lambda)

EXAMPLE 2: A ProStar+113 has the HT and/or LT **half** replaced, due to external cracking--the warranty claim should be:

EGR Cooler pressure test add-on (R12-6892U-1, 0.8hrs)

EGR Cooler Removal/Installation (R12-6892U-20, 5.8hrs)

EGR Cooler half separation/assembly (R12-6892U-3, 0.5)

If applicable ONLY - **LT Core R&R** on bench of 0.3 hrs (ex, 2659-21), **Oil Change** (if HT or LT leaking INTERNALLY), and

Lambda Rep/Relearn (if HT or LT leaking INTERNALLY).

With the warranty claim comments, we need only the basics--"Truck came in with leaking HT and plugged LT. Replaced both cores, oil, and performed lambda relearn/replacement."

[SRT Manual](#)

OTHER RESOURCES

[2010 MaxxForce 11/13 Resource Center \(IK1200548\)](#)

[2010 MaxxForce 11/13 Diagnostic Manual](#)

[2010 MaxxForce 11/13 Service Manual](#)

[HT Tool Instructions \(TL2900093\)](#)

[LT Core Removal/Install Tool Instructions \(TL2900085\)](#)

[ProStar LT Instructions \(iKnow 1201096\)](#)

[TranStar LT Instructions \(iKnow 1201097\)](#)

[WorkStar/CAT LT Instructions \(iKNow 1201098\)](#)

 Hide Details

Feedback Information

Viewed: 20396

Helpful: 70

Not Helpful: 10

No Feedback Found

Copyright © 2016 Navistar, Inc.