



|                          |  |                       |                 |
|--------------------------|--|-----------------------|-----------------|
| <b>Countries:</b>        | RUSSIA, AUSTRALIA, BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, MEXICO, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA, SOUTH KOREA, NEW ZEALAND, PANAMA | <b>Document ID:</b>   | IK1201252       |
| <b>Availability:</b>     | ISIS, FleetSIS   | <b>Revision:</b>      | 6               |
| <b>Major System:</b>     | ENGINES  | <b>Created:</b>       | 1/7/2015        |
| <b>Current Language:</b> | English  | <b>Last Modified:</b> | 2/24/2016       |
| <b>Other Languages:</b>  | NONE   | <b>Author:</b>        | Mujtaba Aidroos |
| <b>Viewed:</b>           | 5174   |                       |                 |

[Less Info](#)

|                                       |                           |                                   |                         |              |                         |                |                    |
|---------------------------------------|---------------------------|-----------------------------------|-------------------------|--------------|-------------------------|----------------|--------------------|
| <input type="checkbox"/> Hide Details | Coding Information        |                                   |                         |              |                         |                |                    |
| <b>Copy Link</b>                      | <b>Copy Relative Link</b> | <b>Bookmark</b>                   | <b>Add to Favorites</b> | <b>Print</b> | <b>Provide Feedback</b> | <b>Helpful</b> | <b>Not Helpful</b> |
|                                       |                           |                                   |                         |              |                         |                |                    |
|                                       |                           | <a href="#">View My Bookmarks</a> |                         |              |                         | 15             | 2                  |

**Title: Big Bore High Pressure Fuel Pump CPA Test Procedure**

**Applies To: EPA 2010 & later MaxxForce 11, 13L and N13 Engines**

## CHANGE LOG

2/24/2016- corrected CAM polarity error in instructions  
 7/06/2015 - Author updated for feedback purposes.  
 06/25/2015 - Updated coding to include New Zealand, Australia, Russia  
 04/27/2015 - Added information about WAC policy letter  
 03/27/2015 - Updated Article Coding  
 03/25/2015 - Initial Article Release

## DESCRIPTION

**Prior to using this article, refer to IK1201061 for 3055-0 and/or IK1201063 for 3055-15.**

This document describes the how to run the 13L high pressure fuel pump (HPFP) test in the Cylinder Performance Analyzer (CPA). The Cylinder Performance Analyzer (12-999-01) assists in diagnosing mechanical defects by monitoring electrical signals from the engine sensors.

For this tests the CPA Tool is connected to the:

- Camshaft position sensor (CMP)
- Fuel Delivery Pressure sensor (FDP)
- Fuel rail pressure sensor (FRP)
- Fuel Pressure Control Valve (FPCV)

If the CPA detects a failed HPFP it will issue a WAC for the HPFP

If the CPA confirms that the HPFP is ok, proceed with other diagnostics and/or open a case file for further instruction. Its recommended to print the CPA HPFP test set-up instructions (that are also displayed in the software)

**WARNING-** When testing a MaxxForce 13, the CPA Tool must only be connected when the vehicle is parked and the parking brake is set. NEVER DRIVE the vehicle with the CPA Tool (or its cables) connected to the engine. The engine could stall without warning.

## SPECIAL TOOLS

| Tool Description                                    | Tool Number                                       | Comments  | Instructions              |
|---|---|---|---------------------------|
| EZ-Tech w/ServiceMaxx and CPA software v6 or higher |   | Download from the EZ-Tech Download Center                                     | <a href="#">IK2900030</a> |
| RP1210 communication device                         |   |   |                           |
| CPA Tool  | OE-11178 or 12-999-01-01 (with blue rubber sides) |   | <a href="#">TL2900079</a> |
| CPA Extension Harness                               | 12-999-01-05                                      | 4 required  |                           |
| Banana Jack breakout (short)                        | 12-999-01-06                                      | 2 required  |                           |
| Banana Jack breakout (long)                         | 12-999-01-08                                      | 2 recommended   | <a href="#">TL2900113</a> |
| Banana test leads                                   | in kit ZTSE4435C                                  | can be used in conjunction with 12-999-01-06 if 12-999-01-08 is not available |                           |
| 180-pin Breakout Box                                | 00-00956-08                                       |   |                           |
| E1 and E2 Harness Overlay (Breakout box overlay)    | 16-00530-00                                       |   |                           |
| 2010 MaxxFORCE 11 & 13 Harness (E1/E2)              | 00-01468-00                                       |   | <a href="#">SFN1064</a>   |

### [Tools Resource Center](#)

**WARNING:** To prevent personal injury and / or death, read all safety instructions in the “Safety Information” section of the *Engine Service Manual* or *Engine Diagnostic Manual*.

.

Park vehicle on a hard, flat surface, turn engine off, set parking brake, and install wheel chocks to prevent vehicle from moving in either direction.

- Always wear safe eye protection when performing vehicle maintenance.

**CAUTION:** To prevent property damage, the Cylinder Performance Analyzer (CPA) is a sensitive and sophisticated piece of equipment and should be handled with care. Exterior damage may adversely affect the functionality of the tool, causing flawed test results.

When testing a MaxxFORCE® 13 engine, connect the CPA tool only if the vehicle is parked and the parking brake is set. Never drive the vehicle with the CPA tool (or cables) connected to the engine because it may stall without warning.

## **CPA HARDWARE INSTALLATION INSTRUCTIONS**

**CAUTION:** Secure the CPA tool and related wiring away from hot and moving engine parts with cable ties while performing tests.

To print out the instructions included in the CPA software, click [13L HPFP CPA instructions](#). These instructions include a photo of the breakout box and cable hookups.

1. Connect cable between port on CPA Tool to USB port on EZ Tech® or other Electronic Service Tool (EST) with CPA and ServiceMaxx installed.
2. Connect RP1210 communication device (ie Nexiq) to the vehicle J1939 datalink connector and the other to the EZtech.


3. Disconnect two connectors (E2 must be removed prior to removing E1) on ECM.
4. Connect the E1 breakout harness connector to the E1 ECM 96 pin connector. Reconnect the second connector (E2) back to the ECM.
5. Connect E1 breakout harness 00-01648-00 connector to the to the E1 engine harness connector that was removed from the ECM.
6. Connect X connector of engine harness 00-01648-00 to X connector of 180 pin breakout box 00-00956-08. (Z connector of engine harness 00-01648-00 is not used).
7. Connect "cam sensor" channel (CMP) on CPA box to ECM breakout box E17 red & E41 black, using 12-999-01-05 and banana jack 12-999-01-06.
8. Connect "crank sensor" channel (FPCV) on CPA box to ECM breakout box E73 black & E25 red, using 12-999-01-05 and banana jack 12-999-01-06.
9. Connect "sensor 3" channel (FRP) on CPA box to ECM breakout box E21 black & E34 red, using 12-999-01-05 and banana jack 12-999-01-08 (or substitute 12-999-01-06 and banana lead from ZTSE4435C).
10. Connect "sensor 4" channel (FDP) on CPA box to ECM breakout box E22 black & E35 red, , using 12-999-01-05 and banana jack 12-999-01-08 (or substitute 12-999-01-06 and banana lead from ZTSE4435C).

NOTE: The two signal adjustment knobs should be turned as far clockwise as possible. Newer CPA tool versions are not equipped with these knobs.

## **CPA TEST INSTRUCTIONS**

Prior to using this article, refer to IK1201061 for 3055-0 and/or IK1201063 for 3055-15.

### **Preliminary Test & CPA Software Requirements**




1. Confirm that the engine runs well enough to complete a ServiceMaxx "High Pressure Fuel Pump Test". Do not proceed until this is confirmed.
2. If the test does not run, refer to [TROUBLESHOOTING- HPFP WILL NOT RUN IN SERVICEMAXX](#) near the end of this article.
3. Verify CPA software is downloaded--check for "Engine Cylinder Performance Analyzer" software in Start menu. If the software is NOT listed, it must be installed prior to continuing.
4. Verify CPA software is updated to version 6.XXX or higher

Refer to [TL2900030 Dealer EZ-Tech and Diagnostic Software Support Resource Center](#) for support to obtain or upgrade software.

### **Service Maxx/ CPA Software Instructions**

To print out the instructions included in the CPA software, click [13L HPFP CPA instructions](#)

1. Key On Engine Off
2. Launch ServiceMaxx.



3. In Service Maxx, Select "Tests" "Cylinder Performance Analyzer"

|                                   |   |
|-----------------------------------|---|
| <b>Base Engine Class</b>          | i783(BB 11 & 13)  |
| Engine Type                       | MaxxForce 11/13 (2010 - 2012)                                 |
| Software Identification           | OEEAASMA  |
| Engine Family Rating Code         |   |
| <b>VIN</b>                        | 1HSDJSJRXCJ553140   |
| <b>Engine Serial Number</b>       | 125HM2Y4111504  |
| <b>Transmission Type</b>          | Manual  |
| Rated Horsepower                  | 450.0 hp  |
| <b>Total Miles</b>                | 333,610.1 miles   |
| Total Fuel Used                   | 48,220.4 gal  |
| Total Engine Hours                |   |
| <b>Time/Date</b>                  | 3:11 PM, 3/16/2015  |
| <b>Dealer Name &amp; Location</b> | Mark Ehlers, Service Engineering, Confixit, Indiana (000000-C |
| <b>Operator</b>                   | MSE   |
| <b>Customer Complaints</b>        | test  |


General User User Group

Please fill in the information table and then press "Proceed" or "Quit" button.  
To Proceed, all **bold** fields must be filled in.


Show "Help" Tipstrip

Proceed (F5) Quit


4. In the CPA window, the CPA Log-In window appears and populates vehicle information. Manually enter operator and customer complaints, and click PROCEED (or F5)




5. In CPA window, select "Tools" "13L HPFP"
6. Start the vehicle and make sure engine coolant temperature is 100 degrees F or greater.




7. In CPA window, the CPA HPFP test window will open. Select "Start Test"




8. "You have selected HPFP test" window will appear. Select "Proceed" (not shown below)




9. In CPA, "Please start test from ServiceMaxx" window will appear.




10. Toggle to the ServiceMaxx window. In ServiceMaxx, Select "Tests" "KOER Tests" "High Pressure Pump Test"



11. When the pretest Information window appears in ServiceMaxx, select "OK"



12. Toggle to the CPA window. In CPA, the HPFP test in process window will appear.




13. In CPA, when the test has completed, a results screen will appear.


If the CPA tool generates a WAC code, replace the High Pressure Fuel Pump.

If the CPA tool shows that the HPFP has passed, continue with further diagnostics or open a Tech Services case file.

The above CPA screen shows the HPFP has passed the test and further diagnostics are needed.




The above CPA screen shows that the HPFP has failed and should be replaced. A WAC code is generated. Refer to [WPL2800115 WPL15-006G Warranty iApproval Requirements](#)



14. In Service Maxx, the test completed screen will appear.
15. Turn off the vehicle. Close CPA and ServiceMaxx programs as necessary. Disconnect all CPA test hardware and reassemble harness connections.
16. CPA test complete--proceed with repairs or return to iKNOW diagnostics.


## **CPA File Attachment to Case Files Instructions**

1. Open the case file in the International@ Service Portalsm.



**Figure 3**

2. From the case file home page, select the BROWSE button.




**Figure 4**

4. Select Engine Cylinder Performance Analyzer folder.
5. Select the Mondat file from the appropriate test recording(s)
6. Verify the Mondat file is under the Attachments section of the case file home screen.

## **TROUBLESHOOTING- HPFP will not run in ServiceMaxx**

### **TEST ENTRY CONDITIONS**

The section is to help troubleshoot when the HPFP test will not run in ServiceMaxx. The following items can be addressed in ServiceMaxx High Pressure Pump session.



1. In the first tab, review the entry conditions which must be met for the HPFP test to run.

| Name                                     | Value            | Units |
|--|------------------|-------|
| AFT DPF Regen Stage                      | REGEN_STAGE_NONE |       |
| AFT Regen Inhibit - Engine Not Warmed Up | Not inhibited    |       |
| Accelerator Pedal Position 1             | 0.0              | %     |
| Brake Switch                             | Released         |       |
| DPF Soot Load                            | 23               | %     |
| Engine Coolant Temperature 1             | 180              | F     |
| Engine Speed                             | 598.5            | RPM   |
| Parking Brake Switch                     | Set              |       |
| SCR Intake Temperature                   | 459.7            | F     |

2. In the "Entry Condition signals" tab, review the current signals and compare to above requirements.

| ID    | Name                            | Value | Undo |
|-------|---------------------------------|-------|------|
| 77532 | Maximum Standstill Engine speed | 1,650 |      |
| 82022 | Low Idle Engine Speed           | 600   |      |
| 82032 | High Idle Engine Speed          | 1,650 |      |

3. In the "Parameters" tab, change any parameters as needed.
4. Perform HPFP test.

### **WARRANTY INFORMATION**

**Special Requirements:**

The Warranty Center will be requiring WAC or case file for High Pressure Fuel Pump replacements. Refer to [WPL2800115](#) [WPL15-006G Warranty iApproval Requirements](#)

**Warranty Claim Coding:**

For all Warranty Coding, see the appropriate iKNow article.

|               |                               |
|---------------|-------------------------------|
| <b>Group:</b> | 12000 - Engine                |
| <b>Noun:</b>  | 454 - High Pressure Fuel Pump |


**Standard Repair Times:**

| Hrs Code                       | Model Engine              | Description   |
|--------------------------------|---------------------------|---|
| 0.5 <a href="#">A12-2158U</a>  | All EPA10 MAXXFORCE 11/13 | Cylinder Performance Analyzer Tool Diagnostics HP Fuel Pump |
| 0.5 <a href="#">A12-2158US</a> | All N13                   | Cylinder Performance Analyzer Tool Diagnostics HP Fuel Pump |

[SRT Manual](#)

**OTHER RESOURCES**

[Master Service Information Site](#)

|  |   |
|--|---|
|  Hide Details | <b>Feedback Information</b>                   |
|  | Viewed: 5173<br>Helpful: 15<br>Not Helpful: 2 |
| No Feedback Found  |   |

Copyright © 2016 Navistar, Inc.