



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tip - USB Port Inoperative Using Multi Media Interface Tester (MIT)

**Models:** 2013 Cadillac ATS  
Equipped with Radio RPO RAO (without UA3)  
2014-2015 Cadillac ATS  
2014 Chevrolet Impala, Silverado 1500  
2015 Chevrolet Colorado, Impala, Silverado, Suburban, Tahoe  
2014 GMC Sierra 1500  
2015 GMC Canyon, Sierra, Yukon Models  
Equipped with Radio RPO IO3

*This PI was superseded to update the recommendation section. Please discard PIC5851B.*

### Condition/Concern

USB port inoperative using Multi-Media Interface Tester (MIT)

MIT Information

The Multi-Media Interface Tester (MIT) Kit # EL-50334-100

Handheld tool in the kit labeled EL-50334-20

### Recommendation/Instructions

Currently, the Multi-Media Interface Tester (MIT) should NOT be used on the above listed vehicles with a base radio for testing USB function. If the MIT is used to test USB function, the USB port may become inoperative. For the port to function again, the ignition will need to be cycled off for 10 minutes OR the battery will need to be disconnected then reconnected. The MIT can be used to test Bluetooth streaming and AUX input "ONLY" if the MIT is powered from the vehicle's auxiliary 12 volt outlet.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION