

 HYUNDAI NEW THINKING. NEW POSSIBILITIES. Technical Service Bulletin	GROUP CAMPAIGN	NUMBER 16-01-048
	DATE November 2016	MODEL(S) Santa Fe Sport (ANa)
SUBJECT: SANTA FE SPORT (ANa) REAR SEAT RELEASE INSPECTION AND REPAIR (SERVICE CAMPAIGN TRR)		

* IMPORTANT	*** Dealer Stock Only ***
<p>Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery.</p> <p>When a vehicle arrives at the service department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.</p>	

Description: On some Santa Fe Sport (ANa) vehicles, the Rear Seat Release Handle may be inoperative. When the seat release handle is pulled in affected vehicles, the rear seatback will not fold down. This bulletin describes the procedure to inspect and if necessary, reconnect the rear seat release cable.

Applicable Vehicles: Certain 2017 Santa Fe Sport(ANa)



Warranty Information:

MODEL	OP. CODE	OPERATION	OP. TIME
Santa Fe Sport	60CA24R0	Inspection	0.2 M/H
Santa Fe Sport	60CA24R1	Inspection & Repair	0.3 M/H

NOTE 1: Submit Claim on Campaign Claim Entry Screen

Service Procedure:

1. To inspect cable attachments, slide the LH & the RH rear seats forward to access the cable connection.



2. Verify that the cable is attached and the cap is secured properly. (see photo)

***If the cable is attached & cap is secured properly, end service procedure here. Use labor Op. 60CA24R0. If not, continue to step 3.**



3. Cable should be attached and cap should be closed. If cable is not attached or cap is not closed, re-assemble each component.



4. Inspect the function of the release.
- With the rear seatback fully raised, pull the release handles on both sides, located in the cargo area.



5. If the seatback folds, then the vehicle is okay. If the seatback does not fold, verify the cable condition again according to steps 1-3 of this TSB.

***Once the seatback folds, the service procedure is complete. Use labor Op. 60CA24R1.**

