

Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan, Touareg Hybrid, Jetta Hybrid, eGolf)	2012- <mark>2016</mark>	All	All	All	All

Condition

27 16 01 February 19, 2016 **2033978** Supersedes Technical Bulletin V271502 dated March 5, 2015 to add additional model year applicability.

Generator Replacement

Charging System inoperative/malfunctions, noise from engine compartment, accessory drive belt damaged or missing.

Technical Background

One or more of the following symptoms are possible:

- Discharged Battery
- No Start
- Battery Indicator illuminated in Instrument Cluster
- "Low Voltage" DTCs in various control modules
- Engine noise
- Accessory Drive Belt damaged or missing

Production Solution

Not applicable.

© 2016 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Bulletin



Service

Tip:

Refer to Elsa for other technical bulletins that may apply to specific vehicles with discharged batteries. These technical bulletins provide important information about intermittent faults and correct battery testing/charging procedures.

If charging system diagnosis for a fault/condition that is electrical in nature leads to the generator as the suspected cause of the concern, it will be necessary to verify the failure of the generator by utilizing the applicable Guided Fault Finding (GFF) Test Plan.

<u>Only replace the generator if the GFF Test plan fails for this component</u>. The completed failed GFF Test plan must be uploaded to Volkswagen via GFF paperless or retained by the dealer (electronically or otherwise), as it may be subject to request.

1 Note:

If the generator has failed in a manner that does not befit scan tool diagnosis (such as a bearing failure), ensure that the reason for the replacement of the part is *thoroughly* documented in the repair order and warranty claim comments.

Warranty

If a generator is replaced, there <u>must be</u> a confirmed failed GFF Test Plan available, or in the event of a mechanical failure of the component, complete and detailed documentation of the reason for the replacement, which must be submitted into the warranty claim comments.

If the Generator is requested to be returned to the Warranty Parts Return Center (WPRC) all documentation must be included with the part return.

Required Parts and Tools

No special parts required.

Tool Description	Tool No:	
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with:	
	ODIS Service and: current online updates	

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2016 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.