



NUMBER: 08-010-16

GROUP: Electrical

DATE: January 28, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETINS 08-126-15, DATED DECEMBER 22, 2015, 18-030-15 REV. C, DATED DECEMBER 22, 2015 AND 21-024-15 REV. D, DATED DECEMBER 22, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. THIS IS A COMPLETE REVISION AND NO ASTERISKS HAVE BEEN USED TO HIGHLIGHT REVISIONS.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-012. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

HELP USING THE wiTECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE wiTECH DIAGNOSTIC APPLICATION WINDOW.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: Diagnostic And System Improvements

OVERVIEW:

This bulletin involves updating the Body Control Module (BCM), Powertrain Control Module (PCM), Transmission Control Module (TCM) with the latest available software. All three modules must be updated in this service action.

MODELS:

2016 (FB) Fiat 500X

**NOTE: This bulletin applies to vehicles within the following markets/countries:
NAFTA.**

NOTE: This bulletin applies to vehicles built on or before October 16, 2015 (MDH 1016XX).

SYMPTOM/CONDITION:**Powertrain Control Module (PCM)**

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find one or more of the following Diagnostic Trouble Codes (DTCs):

- U0402 - Implausible Data Received From TCM.
- P0133 - O2 Sensor 1/1 Slow Response.
- P0171 - Fuel System 1/1 Lean.
- P050D - Cold Start Rough Idle.

In addition, customers may experience one or more of the following concerns:

- Vehicle performance enhancements.
- Clatter or ticking noise from the engine at idle.
- RPM flare at cold start.
- Less than desired idle performance.
- Cold engine RPM surge with gear engagement.

Transmission Control Module (TCM)

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find one or more of the following Diagnostic Trouble Codes (DTCs):

- P0711 - Transmission Fluid Temperature Sensor A Circuit Range-Performance.
- P1CC9 - Unable to Engage Gear.
- P1D98 - Incorrect Gear Ratio Clutch B or D Defective.
- P1DAD - Input Shaft-Output Shaft Direction Correlation.
- U1424 - Implausible Engine Torque Signal Received.

In addition, the customer may also experience one or more of the following transmission related conditions:

- Garage Shifts (Shifting from Park or Neutral into Drive or Reverse).
- Harsh 1-2 upshifts.
- Less than desired accelerator pedal response in Sport and Traction Plus modes.
- RPM flare at engine start.
- Less than desired idle performance when shifting into DRIVE or REVERSE following a cold start.

The following enhancements are included in the software update:

- Vehicle performance enhancements.
- Improve transmission shift enhancements for sand and snow mode.
- Improved paddle shifter operation.

Body Control Module (BCM)

A customer may describe that the remote key is not recognized and doesn't open/close door locks.

In some cases the engine may not start due to the fact that a valid key is not recognized.

Upon further investigation the technician may find the Diagnostic Trouble Codes (DTCs):

- B105A-64 - Doors Lock All-Signal Plausibility Failure.
- B105D-64 - Doors Deadlock Or Unlock Driver-Signal Plausibility Failure.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

REPAIR PROCEDURE:

CAUTION: The Transmission Control Module (TCM), Powertrain Control Module (PCM) and the Body Control Module (BCM) must all be updated to the latest available software at the conclusion of this repair procedure.

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Inspect all modules for latest available software. Are all modules up to date?
 - a. YES>>> This bulletin has been completed, use LOP (18-19-17-9H) to close the active RRT.
 - b. NO>>> Proceed to [Step #2](#).
2. Reprogram the PCM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
3. Reprogram the TCM with the latest available software.
4. Reprogram the BCM with the latest available software.
5. Using wiTECH, restore configuration and align proxi. This routine is available under the "Diagnostic Procedures" tab found on the home, "Vehicle View", page of wiTECH.
6. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared
7. Verify all three modules are programmed with the latest available software.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-17-9H	Module, Body Control, Powertrain Control, Transmission Control - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
18-19-17-9G	Module, Body Control, Powertrain Control, Transmission Control - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 3 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and the dealer found updated software to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash