

Date	Expiration	Release	Page
11.2016	11.2018	1	1(5)

Initial Release:

COOLANT HOSE CLAMP RE-TORQUE

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, re-torque the clamps on specific coolant hoses of the cooling system.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS		
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.		
Model	VIN	Fleet Number
X3-45 Commuter Model Year : 2014, 2015, 2016	The following individual vehicles: 2PCG33495 <u>EC735590</u> , 2PCG33498 <u>EC735602</u> and from 4RKG33497 <u>E9737001</u> up to 4RKG33491 <u>G9737299</u> incl.	From 2490 up to 2789, incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.		

MATERIAL NEEDED

No base material is needed for this bulletin

Replacement parts that may be required depending on clamp condition

Part No.	Description	Qty
992089	HOSE CLAMP / 60MM/80MM	A/R
992086	HOSE CLAMP / 32mm/52mm	A/R

NOTE

Material can be obtained through regular channels.

PROCEDURE

Date	Expiration	Release	Page
11.2016	11.2018	1	2(5)



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.



WARNING

Before proceeding with the following steps, make sure coolant temperature has dropped down to a safe level. The sudden release of pressure from a heated cooling system can result in loss of coolant and possible personal injury (scalding) from the hot liquid.

Overview:

Lift vehicle with mobile column lifts.

Locate flexible hoses below and re-torque clamps to **30 lbf-in.** (Fig. 1 & 2)

Date	Expiration	Release	Page
11.2016	11.2018	1	3(5)





Figure 1

Date	Expiration	Release	Page
11.2016	11.2018	1	4(5)



PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 1 hour.

Date	Expiration	Release	Page
11.2016	11.2018	1	5(5)

OTHER

VBC Bulletin	N/A
Fail Code	05.05
Defect Code	09
Syst. Cond	B
Causal Part	992089

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>

or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type
"ADD" in the subject to receive our warranty bulletins by e-mail.



Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.