

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf	2016 - 2017	1.8T (CXBA,CXBB)	All	AU_GM000001*	AU_HM017228
Golf SportWagen	2016 - 2017	1.8T (CXBA,CXBB)	All	AU_GM000001*	AU_HM510346

Condition

01 16 26 December 20, 2016 2045925

Update Programming, DTCs P039B, P03A5, P03AF, P03B9 stored in the ECM Fault Memory

One or more of the following fault codes may be stored in the ECM Fault Memory:

DTC	Description
P039B	Cylinder 1 Pressure Too High
P03A5	Cylinder 2 Pressure Too High
P03AF	Cylinder 3 Pressure Too High
P03B9	Cylinder 4 Pressure Too High

Note:

DO NOT diagnose or replace any components due to faults P039B, P03A5, P03AF, P03B9 **before** performing the update function as explained in this bulletin.

<u>There are EXCLUDED vehicle VINs listed in the Service portion of this bulletin</u>. Ensure the vehicle you are servicing applies to this technical bulletin content before continuing.

Technical Background

Current ECM software causing erroneous faults.

Production Solution

Improved software implemented into production.

Page 1 of 5 plus attachment



Service

Please note that following vehicles cannot be updated using this bulletin

G	olf
3VW917AU9GM005572	3VW917AU8GM005854
Golf Spo	prtWagen
3VWC17AUXGM502894	3VWC17AU4GM502955
3VWC17AU3GM502896	3VWC17AU0GM502970
3VWC17AU1GM502900	3VWC17AU4GM503099
3VWC17AU3GM502932	3VWC17AUXGM503107
3VWC17AU7GM502934	

Update-Programming Procedure:

Tip:

To Update-Programming using SVM, **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim.

Note:

Prior to launching the ODIS service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VVT-12-02. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.

When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 5054A wireless transmitter head for a flash procedure, please connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.



<u>Critical Warning</u>: The Midtronics battery charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.</u>

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!

• Update the Engine Control Module using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
2016 Golf / Golf Sportwagen	CXBA CXBB	8V0 906 264 F	0001 0002 0003 0004	8V0 906 264 K	0003	3EB1
2017 Golf / Golf SportWagen	CXBA CXBB	8V0 906 264 K	0002	8V0 906 264 K	0003	3EB1

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

ETip:

The SVM Process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.



Warranty

To determine if t Procedures Man	-	dure is co	overed under Wa	rranty, alwa	ays refer	to the W	arranty Policies and
Model(s)	Year		Eng. Code	Trans. Code	VIN Range Fron		n VIN Range To
Golf	2016 - 2017		1.8T (CXBA,CXBB)	All	AU_GM000001*		* AU_HM017228
Golf SportWagen	2016 - 2017		1.8T (CXBA,CXBB)	All	AU_GM000001*		* AU_HM510346
			SAGA	A Coding			
Claim Type: L			Use applic	Use applicable Claim Type 1)			
Service Number:		Damage Code		HST		Damage Location (Depends on Service No.)	
2470		0039				Use applicable when indicated in Elsa (L/R)	
Parts Manufacturer		Golf, Golf SportWagen			3ME 2)		
Labor Operation 3) : Charge Battery			у	27068950 = 10 TU			
Labor Operation 3) : Update Programming			mming	See GFF Time expenditure			
Causal Part: Select Labor Operation			on	01500000			
			Diagnos	stic Time 4)			
GFF Time expenditure		01500000 = 50 TU max.		YES			
Road Test		01210004 = 10 TU		YES			
Technical Diagnosis		01320000 = 00 TU max.		NO			
Claim Comment:	: Input "As	s per Tec	hnical Bulletin 2	045925" in	commen	t section	of Warranty Claim.
1) Vehicle may b	e outside	any Warı	ranty in which ca	se this Tec	hnical B	ulletin is	informational only

Page 4 of 5 plus attachment



2) Code per warranty vendor code policy.

3) Labor Time Units (TUs) are subject to change with ELSA updates.

4) Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

No special parts required.

Tool Description	Tool No.		
	InCharge 940 (INC-940)		
Midtronics Battery Tester/Charger	or		
	GRX3000VAS		
VAS Disgrestie Teel	VAS6150/x & VAS 6160/X with:		
VAS Diagnostic Tool	ODIS Service with current online updates		

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.


Document Control Revision Table				
Instance Number Published Date Version Number Reason For Update				
2045925/1	12/20/16	V011626	Original publication.	



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any component which causes a Volkswagen vehicle to perform outside the normal parameters and specifications approved by Volkswagen Group of America / Volkswagen Group Canada.

Date:	
Dealer Number:	_
Vehicle Identification Number:_	
Repair Order Number:	



Dealer stamp

_____, owner or driver of the above identified Volkswagen, confirm:

"Tuning" as described above (especially power increasing modifications) has NOT been performed on my vehicle.

"Tuning" as described above has been performed on my vehicle and the following components were modified or installed:

<u>TUNING was performed by (Please provide Company name and telephone number, if you wish us to contact them):</u>

I understand that if my Control Module is determined to have been tuned, any damage caused by the tuning of the Control Module (including adverse emissions consequences) will not be covered by VWGoA / VGC warranties.

I am permitting an authorized Volkswagen Dealer to reflash (update) my Control Module, and by doing so, I understand that this process will automatically overwrite (destroy) and permanently delete any tuning program that was previously installed on the Control Module of my Volkswagen vehicle.

By signing below, I fully acknowledge and understand that the tuning program will not be restored and VWGoA / VGC, will not be liable in any way for the loss of tuning data.

Signature of Customer