

Technical Information

Service

105/16 ENU 2130

In the Event of Customer Complaint "loss of power" and if the Turbocharger is Faulty: Checking Exhaust Manifold (105/16)

Model Line: Cayenne Diesel (92A)

Model Year: As of 2013 up to 2017

Subject: **Exhaust manifold**

The turbocharger is damaged by detached parts of the cracked inner part of the manifold. Information:

A faulty turbocharger is diagnosed due to loss of power and when the "Check Engine" warning is

activated.

However, a faulty turbocharger can also be diagnosed if the inner part of the manifold is

damaged.

Date of

Introduction: As of May 24, 2016, a reworked exhaust manifold is installed during production.

Remedial

Action: Before installing a new turbocharger, the inner part of the manifold must be checked and the exhaust

manifold may have to be replaced.

Work Procedure: 1 Remove the turbocharger. ⇒ Workshop Manual '213019 Removing and installing turbocharger'

- Remove exhaust manifold. ⇒ Workshop Manual '261019 Removing and installing exhaust manifold'
- 3 Check inner part of the manifold for cracks and fractures \Rightarrow Checking inner part of manifold. Replace the exhaust manifold if it is damaged.



Checking inner part of manifold

2 Service 2130 ENU 105/16

Technical Information

- 4 Install exhaust manifold. ⇒ Workshop Manual '261019 Removing and installing exhaust manifold'
- 5 Install a new turbocharger. ⇒ Workshop Manual '213019 Removing and installing turbocharger'

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
26100152	Checking exhaust manifold	
26100151	Checking exhaust manifold	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	21300	Turbocharger		
Damage type (SA4)	1711	Stiff, stuck, not enough play		

References:

For removing and installing turbocharger, see ⇒ Workshop Manual '213019 Removing and installing turbocharger'

For removing and installing exhaust manifold, see \Rightarrow *Workshop Manual '261019 Removing and installing exhaust manifold'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS

Tester are the ones that must be followed.

Dealership	Service Manager	 Shop Foreman	 Service Technician		
Distribution		144	C . T		
Routing	Asst. Manager	 Warranty Admin.	 Service Technician	 	

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, 918 Spyder®, Tiptronic®, VarioCam®, PCM®, PDK®, 911®, RS®, 4S®, FOUR, UNCOMPROMISED®, and the model numbers and the distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. Specifications, performance standards, standard equipment, options, and other elements shown are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. The information contained herein is for internal authorized Porsche dealer use only and cannot be copied or distributed. Porsche recommends seat belt usage and observance of traffic laws at all times.

Printed in the USA

Dec 13, 2016 Page 2 of 2