16135 One Touch Fold Seat Release



Reference Number: N16207169 Release Date: December 2016

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the

dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited

Warranty period.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
GMC	Acadia	2017	2017				

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2017 model year GMC Acadia vehicles may have a condition in which the rear cargo area left hand 2nd row seat release handle doesn't release the seat, or requires too much effort to release.
Correction	Dealers are to inspect, and if necessary, adjust the 2nd row seat cable.

Parts


No parts are required for this procedure.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Type	Item
9102782	Inspect Operation of 2nd Row Seat Release - No Further Action Required	0.2	ZFAT	N/A
	Add: Adjust 2nd Row Seat Cable	0.3		

Service Procedure


- 1. Inspect the operation of the 2nd row seat release.
 - If the 2nd row seat releases the seat correctly without extra effort, no further action is required.
 - If the 2nd row seat release handle does not release the seat or requires too much effort, proceed to step 2 and adjust the 2nd row seat release cable.
- 2. Ensure that the 2nd row seat is in the upright position and both recliners are fully locked.



4563488

16135 One Touch Fold Seat Release





4640426

Look under the seat to locate the One Touch Fold (OTF) cable adjuster # 1 (See picture above) and open the slider on the adjuster body.

Note: Do not open the other adjuster (marked with an "X" in the picture above), as it will not help resolve this issue.




4563489

4. To open the adjuster body, pull out and up on the tabs as illustrated above.


Note: You may have to remove some cable ties used to secure the adjuster to the bottom of the seat to gain proper access to the adjuster body.

16135 One Touch Fold Seat Release









4563490

Important: Some early built vehicles may not be equipped with the second adjuster. If there is no adjuster found, proceed to Step 6.

5. Locate the OTF cable adjuster (2) under the 3rd row cup holder in the quarter trim panel. Refer to *Quarter Trim Panel Cup Holder Replacement - Left Side* in SI for the removal of the cup holder. Open the cable adjust slider.

Important: Seats must be in upright position and both recliners fully locked prior to closing the cable adjusters. If recliners are not both locked, potential for cable system to hold open one or both recliners exists.

- 6. Move and adjust the tension on the cable adjuster and close the adjuster under the seat first.
- 7. If equipped, move and adjust the cable adjuster and close adjuster in quarter trim.
- Verify release lever function and verify both recliners are locked by returning seat back to the upright position and pushing on each side of seat back to confirm recliners are locked.

Important: It may take more than one attempt at adjustments to get the seat to operate as intended. Repeat steps until the concern is corrected.

16135 One Touch Fold Seat Release



Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service through December 31, 2017, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

GLOBAL SAFETY FIELD INVESTIGATIONS DCS4290 URGENT - DISTRIBUTE IMMEDIATELY

Date: December 12, 2016

Subject: 16135 - Service Update

One Touch Fold Seat Release

Models: 2017 GMC Acadia

To: All General Motors Dealers

General Motors is releasing Service Update 16135 today. The total number of U.S. vehicles involved is 27,483. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated December 12, 2016. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS