

Service Bulletin

File in Section:

Bulletin No.: 16-NA-180

> Date: July, 2016

TECHNICAL

Malfunction Indicator Lamp (MIL) ON, Reduced Engine Power or No-Start, DTCs Set Subject:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Astra, Mini HB5, Onix, Spark	2016	2016			RPO L5Q, LV7 or LWT	All
Holden	Spark, M400						
Opel	Astra, Karl						

Involved Region or Country	North America, Belgium, Germany, Denmark, Italy, Korea, Netherlands		
Condition	Some customers may comment on a reduced engine power or no-start condition along with a MIL and DTCs. Technicians may find multiple DTCs set. Note: 5V reference DTCs should be stored at the same time if the DTCs are related to this software issue. If the DTCs are set individually, perform the diagnostics per SI.		
Cause	Due to a software anomaly, P0606 or 5V Ref DTCs (P0641, P0651, P0697, P06A3) may be set.		

Correction

Update the ECM to the latest software and calibration available. Refer to Engine Control Module Reprogramming with SPS in SI.

Note: Do not replace the ECM to correct this condition. Follow ECM reprogramming instructions in SI.

Warranty Information

Labor Operation	Description	Labor Time	
2881068* (North America)	Engine Control Module Reprogramming with SPS to correct P0606, P0641, P0651, P0697, and P06A3 DTCs	0.4 hr	
2810075 (All Other Countries)	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time	
*This is a unique Labor Operation for Bulletin use only.			

Version	2
Modified	July 18, 2016 – Updated Models, Added Note in Condition statement and added/ specified labor operations per involved region.