

MIL "ON" P023400 - Turbocharger/Supercharger "A" Overboost Condition

Service Category Engine/Hybrid System

Section Engine Control

Market USA

Lexus Supports
ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2015 - 2016	NX200T	

Introduction

Some 2015 – 2016 model year NX 200t vehicles equipped with 8AR-FTS engines may exhibit a MIL "ON" condition Diagnostic Trouble Code (DTC) P023400 (Turbocharger/Supercharger "A" Overboost Condition). The Engine Control Module/ECM (SAE Term: Powertrain Control Module/PCM) logic has been modified to reduce the possibility of this condition occurring. Follow the Repair Procedure in this bulletin to address this condition.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EG1629	Reprogram ECM (PCM)	0.4	89661-78052	8A	99

APPLICABLE WARRANTY

- This repair is covered under the Lexus Federal Emission Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

MIL "ON" P023400 - Turbocharger/Supercharger "A" Overboost Condition

Parts Information

DRIVETRAIN	PART NUMBER		PART NAME	QTY
	PREVIOUS	NEW		
FF/FF F-Sport	89661-78050 89661-78051 89661-78052	89661-78053	Computer, Engine Control (ECM/PCM)	-
AWD	89661-78060 89661-78061 89661-78062	89661-78063		
AWD F-Sport	89661-78070 89661-78071 89661-78072	89661-78073		
-	00451-00001-LBL		Authorized Modification Labels	1

NOTE

- The ECM (PCM) should NOT be replaced as part of the Repair Procedure.
- Authorized Modification Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through *Dealer Daily – Parts – Dealer Support Material Order*.

MIL "ON" P023400 - Turbocharger/Supercharger "A" Overboost Condition

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*	ADE	TS2UNIT	1
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 11.20.019 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- The Diagnostic Tester is NOT recommended for flash reprogramming. Please use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit techinfo.toyota.com for more information regarding J2534 reprogramming.



SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	00002-MCGR8	1

* Essential SST.

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Calibration Information


MODEL	DRIVETRAIN	CALIBRATION ID		VDS	
		PREVIOUS	NEW		
NX 200t	FF/FF F-Sport	896637805200	896637805500	YARBZ	
		896637805300			
		896637805400			
	AWD	896637806200	896637806500		BARBZ
		896637806300			
		896637806400			
	AWD F-Sport	896637807200	896637807500		
		896637807300			
		896637807400			

MIL "ON" P023400 - Turbocharger/Supercharger "A" Overboost Condition

Repair Procedure

1. Confirm the condition.
Using Techstream, perform a Health Check. Was DTC P023400 retrieved?
 - **YES** – Go to step 2.
 - **NO** – This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
2. Check for the Authorized Modifications Label affixed to the vehicle in the location shown below. Confirm if the ECM (PCM) calibration has been updated.
Is the calibration ID listed NOT the latest ECM (PCM) calibration?
 - **YES** – Go to step 3.
 - **NO** – This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

Figure 1. Location of Authorized Modifications Label on 2015 – 2016 NX 200t



1	Replacement ECM (PCM) Part Number (i.e., 89661-78053 or 89661-78063)
2	New Calibration ID (i.e., 896637805500 or 896637806500)
3	Dealer Code

4	Date Completed
5	This SB Number

MIL "ON" P023400 - Turbocharger/Supercharger "A" Overboost Condition

Repair Procedure (Continued)

3. Flash reprogram the ECM (PCM).

NOTE

- The GR8 Battery Diagnostic Station **MUST** be used in Power Supply Mode to maintain battery voltage at 13.5 volts while flash reprogramming vehicle.
- For details on how to use the GR8 Battery Diagnostic Station, refer to the [GR8 Instruction Manual](#) located on the Technical Information System (TIS), *Diagnostics – Tools & Equipment – Battery Diagnostics*.

Follow the procedures outlined in Service Bulletin No. [L-SB-0021-14](#) "Techstream ECU Flash Reprogramming Procedure," and flash the ECM (PCM) with the NEW calibration file update.

4. Install the Authorized Modifications Label.
 - A. Using a permanent marker, enter the following information on the label:
 - ECM part number [*Refer to the **Parts Information** section for the **NEW PART NUMBER***]
 - Calibration ID(s) [*Refer to the **Calibration Information** section for the **NEW CALIBRATION ID***]
 - Dealer Code
 - Repair Date
 - Change Authority [**This bulletin number**]
 - B. Affix the Authorized Modifications Label to the vehicle at the location shown in Figure 1. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.
5. Test drive the vehicle to confirm the DTC does NOT reset.