TECHNICAL INSTRUCTIONS

FOR

SSC G0G

CERTAIN 2015-2016 MY SIENNA


OXYGEN SENSOR REPLACEMENT

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold at least one of the following certification levels:

- Certified Technician (Any specialty)
- Expert Technician (Any specialty)
- Master Technician
- Master Diagnostic Technician

Always check which technicians can perform the recall remedy by logging on to <u>https://www.uotdealerreports.com</u>. It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this SSC and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.

III. PREPARATION

A. PARTS

| Part Number | Part Description | Quantity |
|-------------|------------------|----------|
| 89465-08140 | SENSOR, OXYGEN* | 1 |

B. TOOLS & EQUIPMENT

Standard hand tools
Torque Wrench

SST- These are essential special service tools that the dealership should have.


| Part Number | Name | Quantity |
|----------------|------------------|----------|
| 09224-00010-01 | O2 Sensor Wrench | 1 |

C. MATERIALS


- Protective eyewear
- Protective gloves

IV. BACKGROUND


The subject vehicles are equipped with an Oxygen Sensor which could experience wire degradation inside the Oxygen Sensor wiring harness caused by vehicle vibration during normal operation. If this occurs, the vehicle will illuminate the check engine light.




V. COMPONENTS




VI. REPLACE THE OXYGEN SENSOR





c) Engage the harness clamp to connect the oxygen sensor wire to the vehicle.



Guide K1500440017

8. REINSTALL THE LEFT INSTRUMENT FINISH PANEL

- a) Engage the 3 guides and reinstall the panel.
- b) Reinstall the clip.


VERIFY REPAIR QUALITY

If you have any questions regarding this update, please contact your area representative.

VII. APPENDIX

_

A. CAMPAIGN DESIGNATION DECODER



B. CAMPAIGN PARTS DISPOSAL

As required by Federal Regulations, please make sure all campaign parts (original parts) removed from the vehicle are disposed of in a manner in which they will not be reused, **unless requested for parts recovery return.**