

Toursto Cumporto

Entune Audio Head Unit Software Update (Fujitsu Ten)

Service

Category Audio/Visual/Telematics

Section	Navigation/Multi Info Display	Market USA	ASE Certification
---------	-------------------------------	------------	-------------------

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2016	Camry, Camry HV, Corolla, RAV4, RAV4 HV	

REVISION NOTICE

April 4, 2016 Rev1:

The Software Update section has been updated.

Any previous printed versions of this bulletin should be discarded.

Introduction

Some 2016 model year vehicles equipped with Entune[™] Audio (version UU.10.48), Entune[™] Audio Plus (version EU.10.68 or EU.20.05 or EU.20.08), or Entune[™] Premium Audio (CU.10.71 or CU.10.72 or CU.20.05 or CU.20.08) may exhibit one or more of the following conditions:

- Swiping feature inoperative on APPs or Setup screens.
- Meijer Department Store is intermittently pronounced "Mee-jer".
- Number of transferred contacts is not updated.
- Slacker skips 2 songs when using steering wheel controls.
- Starting Pandora via Voice Recognition is intermittently inoperative.
- Transitioning from BT Audio to Entune, no sound is output (iPhone and Android).
- FM mode will show the incorrect number of available stations intermittently.
- Voice Recognition will not start intermittently.
- Audio is intermittently not displayed on the home screen.
- Rumbling sound when no audio is playing.
- Intermittent "Message list could not be loaded" is displayed when retrieving messages.
- Audio information does not match between the Head Unit and Instrument Cluster.
- Instrument Cluster has incorrect display of XM channels.
- Panoramic camera view is intermittently inoperative.
- Scout voice guidance has rear speakers muted.
- USB Audio Playback resets after key cycle.

Warranty Information

OP CODE	DESCRIPTION	DESCRIPTION TIME MODEL		OFP	T1	T2
	Software Update	0.3	Camry, Camry HV	86804-06180 86804-06190 86140-06660 86140-06670		
			Corolla	86140-02460 86140-02470 86804-02070	73	
EL1521			RAV4	86804-0R030 86804-0R040 86140-0R170 86140-42110 86140-0R180 86804-42100 86804-42110 86140-42460		74
			Prius C	86140-52330 86804-52040		

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST) PART NUMBER		HEAD UNIT	APPLICABLE FILE ON USB DRIVE	QTY
	01040-FJTSU-16A	Entune™ Audio	15TBDANA-CA01_1106.kwi	
USB Drive Firmware		Entune™ Audio Plus	15TDDANA-CA01_2014.kwi	1
Update – Fujitsu Ten*		Entune™ Premium Audio	15TDANNA-CA01_2014.kwi	

Required Tools & Equipment (Continued)

MULTIMEDIA SOFTWARE FILE DOWNLOAD

The Multimedia software update file may also be downloaded directly from this Service Bulletin by clicking on the file name in the table above. The file may be saved directly to a commonly-available blank USB flash drive.

For USB flash drive requirements and download instructions: Refer to the Technical Information System (TIS): *Diagnostics – Calibrations – Reference Documents – "Multimedia Software Download Instructions"*

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

1. Confirm the audio system type by checking the Panel ID printed above the top-right or bottomright of the display.

Figure 1

ADIO APPS	AUDIO SEEK> <track< th=""></track<>
AUDIO APPS HOME Userer 200 10 10 10 10 10 10 10 10 10 10 10 10 1	PWR-VOL AUGIO PWR-VOL AUGIO Brades graconsce
1 Corrolla	3 Camry/Camry HV
2 RAV4	4 Prius C

Software Update (Continued)

MODEL	MODEL YEAR	ENTUNE™ AUDIO	ENTUNE™ AUDIO PLUS	ENTUNE™ PREMIUM
Camry, Camry HV	Camry, Camry HV		N/A	100612 100613
Corolla		100571	100570	100569
RAV4	2016	100573 100581	100574 100582	100575 100576 100583 100584
Prius C		100629	N/A	100628

- 2. Insert the USB Drive SST into the vehicle USB port.
- 3. Start the engine.
- 4. Wait for the screen to be displayed.

Figure 2.



Software Update (Continued)

5. Wait until the USB source icon highlights and displays the USB name with the icon.



- 6. Go to the Setup screen.
 - A. For Entune[™] Audio. Press the SETUP button on the panel.

Figure 4.

2

RAV4



Prius C

Software Update (Continued)

- B. For Entune[™] Audio Plus / Entune[™] Premium Audio:
 - (1) Press the APPS button on the left of the panel.



Figure 6. Prius C



NOTE

If Entune pop-up displays, select OK.

Figure 7.



(2) Select Setup on the Apps screen.

Figure 8.



Software Update (Continued)

7. Select General on the Setup screen.

Figure 9.



8. Select *Software Update* from the list on the General Settings screen.

HINT

Scroll down the list until *Software Update* is displayed.

Figure 10.



9. Select *Update* on the Software Update screen.

Figure 11.



Software Update (Continued)

NOTE

If software has been detected properly, a *"New Software was found."* pop-up will be displayed.

Figure 12.

Model ID:13TDANNA-CA01 Hard No.:86100-02100	SAM ID : AEAIBUVMTG			
New software was found.				
Device Driver :	AU.20.01 AU.30.08			
Audio :	AU.26.61 AU.30.08 🐺			
Detail	Update Software			

10. Verify that the new software is up-to-date on the Software Update screen.

NOTE

Update Software is enabled only if there is an update newer than the current software.

Figure 13.



Software Update (Continued)

Software Version Information

	Entune™ Audio		Entune™ Audio Plus		Entune™ Premium Audio	
		New Version		New Version		New Version
Туре	Current Version	16 Corolla 16 Rav4 16 Camry 16 Prius C	Current Version	16 Corolla 16 Rav4	Current Version	16 Corolla 16 Rav4 16 Camry 16 Prius C
Operating System		-	EU.10.68 EU.20.05 EU.20.08	-	CU.10.71 CU.10.72 CU.20.05 CU.20.08	-
Device Driver		UU.11.06		EU.20.14		CU.20.14
Audio		UU.11.06		EU.20.14		CU.20.14
Navigation		-		-		-
Bluetooth	UU 10 48	UU.11.06		EU.20.14		CU.20.14
GUI	00.10.10	UU.11.06		-		-
Middle ware		UU.11.06		EU.20.14		CU.20.14
Kernel		UU.11.06		EU.20.14		CU.20.14
Voice Recognition		-		EU.20.14		CU.20.14

11. Select *Update Software* on the Software Update screen.

Figure 14.

Software Update Model ID:13TDANNA-CA01 Hard No.:86100-02100	SAM ID : AI	EAIBUVMSW	D
	Current	New	
Operating System :	AU.30.08	XXXXXX	\$
Device Driver :	AU.30.08	XXXXXX	
Audio :	AU.30.08	XXXXXX	¥
Detail	Updat	e Software	

Software Update (Continued)

12. Select Yes on the "Would you like to start the software update?" pop-up.

Figure 15.



NOTE

Entune[™] Audio Plus only: Select left box on the *"This preset is currently empty. Would you like to save [XXXX] as a preset?"* pop-up.

Figure 16.

Figure 17.



13. This unit begins installation.

NOTE

Do NOT turn off ACC before the software is ready for updating.

oftware Update	2
Installing the new s	software
1 ⁵	
Please keep the media and do not turn off the	inserted e engine.
Installing 1 of	12

Software Update (Continued)

14. When "The software is ready for updating." Displays, cycle the ignition OFF and wait for 30 seconds. Then cycle the ignition ON again.

Figure 18.



15. Wait for the audio system to finish the software update.

NOTE

Do NOT turn off ACC before the next Toyota logo screen displays.

Figure 19.

Figure 20.



16. When the Toyota logo screen is displayed, the update is finished.



17. Remove the USB Drive SST from the vehicle USB port.

Software Version Confirmation

1. Wait for the Select Audio Source screen to be displayed.



- 2. Perform steps 6-9 of the Software Update procedure to re-enter the Software Update screen.
- 3. Verify that the software information is updated on the Software Update screen.

	Entune™ Audio		Entune™ Audio Plus		Entune™ Premium Audio	
Туре	New Version		New Version		New Version	
	16 Corolla 16 Rav4 16 Camry 16 Prius C	M/D/Y	16 Corolla 16 Rav4	M/D/Y	16 Corolla 16 Rav4 16 Camry 16 Prius C	M/D/Y
Boot	UU.11.06		EU.20.14		CU.20.14	
Voice Recognition	-		EU.20.14		CU.20.14	
GUI	UU.11.06		-		-	
Audio	UU.11.06		EU.20.14		CU.20.14	
Bluetooth	UU.11.06		EU.20.14		CU.20.14	
Navigation	-	Updated	-	Updated date		
Device Driver	UU.11.06	date (If no GPS	EU.20.14	(If no GPS signal, date	CU.20.14	Updated date (If no GPS
Kernel	UU.11.06	signal, date	EU.20.14	may not be	CU.20.14	signal, date may
Operating System	-	accurate)	-	accurate)	-	not be accurate)
Middle ware	UU.11.06		EU.20.14		CU.20.14	
Power	-		EU.20.14		CU.20.14	

New Software Version Information