

Abnormal ("Squeak") Noise From Rear Suspension Over Uneven Road

Service Category Suspension

Section Rear Suspension

Market USA

Toyota Supports
ASE Certification 

Applicability


YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2014	Highlander, Highlander HV	

Introduction

Some 2014 model year Highlander and Highlander HV vehicles may exhibit an abnormal noise, like a "squeak/squawk/groan" type noise, from the rear suspension when traveling over uneven roads which may become more pronounced in colder ambient temperatures. The abnormal noise may be caused by the Rear Trailing Arm bushing. An updated Rear Trailing Arm Assembly is available. Follow the Repair Procedure in this bulletin to address this condition.

Refer to the video link below for an example of the squeak/squawk/groan noise condition:
[Highlander & HV "Squeak"/Squawk/Groan Noise Example](#)

Figure 1.



1	Rear Trailing Arm Assembly Bushing
----------	------------------------------------

Abnormal ("Squeak") Noise From Rear Suspension Over Uneven Road

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	PLANT	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
Highlander	TMMI	4WD	5TDBKRFH#ES058013
			5TDDKRFH#ES050777
			5TDJKRFH#ES057924
		2WD	5TDKKRFH#ES030575
			5TDYKRFH#ES028596
			5TDZARFH#ES007980
			5TDZKRFH#ES031683
Highlander HV		4WD	5TDDCRFH#ES006515

Warranty Information

OP CODE	DESCRIPTION	TIME	OPF	T1	T2
482091	R & R Rear Trailing Arm Assembly (One Side)	1.0	48760-0E050	91	99
Combo A	Opposite Side	0.2	48780-0E060		

APPLICABLE WARRANTY

- This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Parts Information

PART NUMBER	PART NAME	QTY
48760-0E050	Arm Assy, Trailing, RR RH	1
48780-0E060	Arm Assy, Trailing, RR LH	1

Abnormal ("Squeak") Noise From Rear Suspension Over Uneven Road

Repair Procedure

1. Confirm the condition.
2. Using chassis ears or equivalent, test drive over uneven road surfaces, such as turning into a sloped driveway, to verify concern is coming from bushings.

HINT

Applying soapy water to the suspected bushing may temporarily diminish the noise intensity, assisting to identify the source of the noise.

Is a "squeak/squawk/groan" type noise present?


- YES — Go to step 3.
- NO — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

3. Replace BOTH Rear Trailing Arm Assemblies even if only one side is emitting the "squeak/squawk/groan" type noise.

Refer to the Technical Information System (TIS), applicable model and model year Repair Manual to complete the procedure:

- 2014 Highlander:
Suspension – Rear Suspension – "[Rear Trailing Arm: Removal](#)"
- 2014 Highlander HV:
Suspension – Rear Suspension – "[Rear Trailing Arm: Removal](#)"
- 2014 Highlander:
Suspension – Rear Suspension – "[Rear Trailing Arm: Installation](#)"

Figure 2.



1	Wooden Block
2	Jack

Abnormal ("Squeak") Noise From Rear Suspension Over Uneven Road

Repair Procedure (Continued)

- 2014 Highlander HV:
Suspension – Rear Suspension – ["Rear Trailing Arm: Installation"](#)

NOTICE

Support the rear No. 2 suspension arm assembly until reinstallation of the Rear Trailing Arm Assembly is complete.

4. Test drive vehicle to verify no abnormal noise is present.