

NUMBER: 07-002-16 REV. A

GROUP: Cooling

DATE: August 16, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 07-002-16, DATED AUGUST 04, 2016, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS** AND INCLUDE UPDATED BUILD DATES.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-079. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Thermostat Housing Replacement

OVERVIEW:

This bulletin involves inspecting the bleed screw on the thermostat housing and if necessary replacing the thermostat housing.

MODELS:

2016 (DS) Ram 1500 Pickup 2016 (DX) Ram Truck (Mexico)

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA, EMEA and LATAM.

NOTE: This bulletin applies to vehicles built on or after **September 09, 2015 (MDH 0909XX) and on or before April 17, 2016 (MDH 0417XX)** equipped with 3.6L V6 24V VVT Engine (Sales Code ERB).

SYMPTOM/CONDITION:

The customer may describe a coolant leak at the thermostat housing bleed screw.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the following diagnosis procedure. For all other customers that describe the symptom/condition listed, normal diagnostics should be performed.

- 1. Inspect the thermostat housing bleed screw for visible leaks (Fig. 1).
- 2. Is coolant leaking from the bleeder screw?
 - a. YES>>> Replace thermostat housing. Proceed to repair procedure, Step #1.
 - b. NO>>> Proceed to Step #3.
- 3. Remove the throttle body assembly to gain access to the bleeder screw. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>14 Fuel System/Fuel Injection, Gas/Throttle Body/Removal>3.6L.
- 4. Tighten the bleed screw to 3 N·m (26 in.lbs).
- 5. Does the bleed screw achieve the specified torque?
 - a. YES >> Reinstall the throttle body assembly. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>14 Fuel System/Fuel Injection, Gas/Throttle Body/Installation>3.6L. Use LOP (07 40 05 99) to close the active RRT.
 - b. NO>> Proceed to Step #1.

PARTS REQUIRED:

Qty.	Part No.	Description	
1	04893865AB	Thermostat Housing	
1	53032763AA	Gasket, Throttle Body	
(AR)	68163848AB	Coolant	

REPAIR PROCEDURE:

 Replace the thermostat housing (Fig. 1). Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 07 -Cooling/Engine/Thermostat/Removal/Installation>3.6L.




Fig. 1 Thermostat Housing

- 1 Thermostat Housing
- 2 Bleed Screw

 Fill cooling system. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: 07 - Cooling/Standard Procedure>Standard Procedure - Filling - 3.6L.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
07-40-05-99	Bleed Screw, Inspect And Fill Cooling System (1 - Semi-Skilled)	1 - Engine Repair And Performance	0.4 Hrs.
07-40-05-9A	Housing, Thermostat Inspect And Replace (1 - Semi-Skilled)	1 - Engine Repair And Performance	0.7 Hrs.

FAILURE CODE:

ZZ	Service Action	
----	----------------	--