

## Service Bulletin

Bulletin No.:

n No.: 16-NA-345 Date: October, 2016

## TECHNICAL

Subject:	Turn Signals Engage When Depressing the Brake Pedal
----------	---

Brand:	Model:	Model Year:		Breakpoint:		Engine	Transmission:
Branu.		from	to	from	to	Engine:	
Chevrolet	Express	2017	2017	SOP	H1129315		
GMC	Savana						

Involved Region or Country	North America, Middle East and Israel
Additional Options (RPO)	RPO V4D
Condition	Some customers may comment that the turn signals engage when pressing on the brake pedal.
Cause	This condition may be caused by a software anomaly.

## Correction

- For vehicles without UY7, update the body control module (BCM) with the latest software. Refer to *Body Control Module Programming and Setup* in SI.
- **DO NOT** perform this bulletin on vehicles with UY7 RPO. This change will result in the loss of stop lamp functionality for the trailer lamps if performed. Engineering is developing a solution for these vehicles.

**Note:** The solution will not be a SW solution. The UY7 (trailering capability) will either need to be removed or the vehicle will need to be rewired to retain proper trailering operation.

## Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time	
2881138*	Body Control Module Reprogramming with SPS (RPO V4D)	0.5 hr	
*This is a unique Labor Operation for Bulletin use only.			

Version	2
Modified	Oct. 19, 2016 – Removing references to RPO UY7 from Additional Options and Warranty Information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION