GM Bulletin No.: 31770

Date: April 2016

SERVICE UPDATE

SUBJECT: Service Update for Inventory and Customer Vehicles

Advanced Park Assist Operation Expires with Base Warranty

MODELS: 2016 Cadillac CTS-V

This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

PURPOSE

This bulletin provides a service procedure to reprogram the advanced parking assist control module on **certain** 2016 model year Cadillac CTS-V vehicles. These vehicles may park out of position when using the advanced park assist feature.

This service procedure should be completed as soon as possible on involved vehicles currently in dealer inventory and customer vehicles that return to the dealer for any type of service during the New Vehicle Limited Warranty coverage period.

VEHICLES INVOLVED

All involved vehicles are identified by VIN in the Global Warranty Management System – Investigate Vehicle History Application. Dealership technicians should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

Additionally, a list of involved vehicles currently in dealer inventory can be found in GlobalConnect, under Departments, Service, Field Action Inventory Reports (US) or attached to the GlobalConnect message (Canada) used to release this bulletin. Customer vehicles that return for service, for any reason, and are still covered under the vehicle's base warranty should also be checked for vehicle eligibility.

PART INFORMATION

No parts are required for this procedure.

SERVICE PROCEDURE

Note: Carefully read and follow the instructions below.

- Do NOT attempt to order the calibration number from GM Customer Care and Aftersales.
 The calibration numbers required for this service procedure are programmed into control
 modules via a Multiple Diagnostic Interface (MDI) with the calibration update. If you
 cannot access the calibration, call the Techline Customer Support Center and it will be
 provided.
- Do NOT program a control module unless directed to by a service procedure or a service bulletin. If the control module is not properly configured with the correct calibration software, the control module will not control all of the vehicle features properly.
- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. When required, install the *EL-49642* SPS Programming Support Tool to maintain system voltage. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Turn OFF or disable systems that may put a load on the vehicles battery such as; interior lights, exterior lights (including daytime running lights), HVAC, radio, etc.
- During the programming procedure, follow the SPS prompts for the correct ignition switch position.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.
- 1. Install *EL-49642* SPS programming support tool.
- 2. Access the Service Programming System (SPS) and follow the on-screen instructions.
- 3. On the SPS Supported Controllers screen, select K41 Front and Rear Parking Assist Control Module Programming and follow the on-screen instructions.
- 4. On the SPS Supported Controllers screen, select K41 Front and Rear Parking Assist Control Module Configuration and follow the on-screen instructions.
- 5. At the end of programming, choose the "Clear All DTCs" function on the SPS screen.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time
9102174	Parking Assist Control Module Reprogramming with SPS	0.3

DEALER PROGRAM RESPONSIBILITY

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.



31770 - Service Update - Advanced Park Assist Operation Updated Date: Apr 21, 2016 13:35 ET

GLOBAL SAFETY FIELD INVESTIGATIONS DCS4007 URGENT - DISTRIBUTE IMMEDIATELY

Date: April 21, 2016

Subject: 31770 - Service Update

Advanced Park Assist Operation

Models: 2016 Cadillac CTS-V

To: All Cadillac Dealers

General Motors is releasing Service Update 31770 today. The total number of U.S. vehicles involved is approximately 436. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated April 22, 2016. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS

31770 Bulletin.pdf

About this Alert

Reference Number: GCUS-3-514 Published to: Home Page

Version: 1.0

Alert Type: Service Update

Original Published Date: Apr 21, 2016 13:35 ET

Expires: Jun 20, 2016 0:00 ET Contact : loren.rusk@gm.com