

GROUP: Brakes

DATE: March 23, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 05-001-16, DATED JANUARY 13, 2016, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS** AND INCLUDE REMOVING LATAM MARKET FROM BULLETIN.

HELP USING THE WITECH DIAGNOSTIC APPLICATION FOR FLASHING AN ECU IS AVAILABLE BY SELECTING "HELP" THEN "HELP CONTENTS" AT THE TOP OF THE WITECH DIAGNOSTIC APPLICATION WINDOW.

THE WITECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Flash: ABS Module Electronic Parking Brake Enhancements

OVERVIEW:

This bulletin involves updating the Anti-lock Brake System (ABS) module software.

MODELS:

2016	(FB)	Fiat 500X
2015 - 2016	(BU)	Jeep Renegade

NOTE: This bulletin applies to vehicles within the following markets/countries: **NAFTA, APAC and EMEA**.

NOTE: This bulletin applies to 2016 (FB) and (BU) vehicles built on or before December 23, 2015 (MDH 1223XX).

SYMPTOM/CONDITION:

The customer may describe:

- The key may get stuck in the ignition key cylinder.
- The Electronic Parking Brake (EPB) does not engage with the "Auto Apply" feature selected.

NOTE: The Parking Brake will apply when the switch is manually activated.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

- Reprogram the ABS module with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.
- Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
- NOTE: Upon completion of this ABS flash reprogramming session, an additional 10 second key cycle (off to on) may be required to mature an active DTCM (Drive Train Control Module) DTC to stored allowing DTC to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-10-9C	Module, Anti-lock Brake System (ABS) - Reprogram (0 - Introduction)	4 - Chassis	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 3 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash