

Date: 27.07.2016

# Model: Evora Models from Start of Production up to '15 MY Inclusive

Number: 2016/15

Copy files should be maintained by:

Service Manager	Service Reception	Supervisor	Parts Manager	

## TITLE:

Procedure to recover the ECU if an "ECU Comms Failure" message appears in the instrument panel display screen.

## **REASON:**

Under certain conditions such as a discharged battery or an interrupted programming procedure, the vehicle ECU (Electronic Control Unit) may lose communication with other engine management systems, resulting in:

- An "ECU Comms Failure' message being displayed in the RH instrument panel display screen.
- Vehicle non-start even after sufficient battery capacity is restored.
- Lotus TechCentre unable to communicate with the engine management system to program the ECU.
- Previously only repairable by replacement of the ECU or return of the ECU to the factory.



## ACTION:

NOTE: This situation may be avoided by always ensuring that the vehicles battery is connected to a battery conditioner during storage for extended periods of time as well as ensuring that the battery has sufficient charge before attempting to update or programming the ECU.

A file has been added on the Lotus Dealer Portal which may restore communication between the Lotus TechCentre and the ECU. In the event that you are presented with an Evora NA (280) or Evora S (350) model displaying the "ECU Comms Failure" message then the following procedure should be attempted prior to contacting Lotus Cars. Once downloaded from the Lotus Dealer Portal, the file can be installed into any affected vehicle using your Lotus TechCentre laptop\* and VCD (Vehicle Communication Device) part number T000T1472F.

\*Although Lotus TechCentre is not required for the update procedure, the dedicated TechCentre laptop must be used as the required VCD software is already installed.

#### Lotus TechCentre Laptop Preparation:

- From the home page of the Lotus Dealer Portal the T6 ECU recovery zip file is located in: Aftersales>TechCentre & Production ECM Program Information category.
- Download the ZIP file and save it to the desktop of your Lotus TechCentre laptop. Note: Downloading view shown using Google Chrome, downloading procedure may vary dependant on laptop operating system and web browser used.



## LOTUS CARS LIMITED

Potash Lane Hethel Norwich Norfolk NR14 8EZ England T +44 (0) 1953 608 000 F +44 (0) 1953 608 514 www.grouplotus.com Registered Office: Potash Lane Hethel Norwich Norfolk NR14 8EZ in England No. 895081 VAT Reg No. GB 105 9863 55 CARS

Bulletin number 2016/15 continued Page 2

Once downloaded onto desktop of the Lotus TechCentre laptop:

	🗐 WinZip - T6_ECU_FIX.z	ip		
T6_ECU_FI	File Actions Options Help			
<b>6</b> .	New Open Favorit	es Add E	Extract View	CheckOut Wiza
T6_ECU_FIX	Name			
	SEfi_prot.dll Efi_prot.exe Prog_T6_ECU_FIX.bat T6_ecu_fix.crp		4.	
	Extract			?
	Extract to: C:\Documents and Settings\334	36ap\Desktop		Extract
	- Files	Folders/drives:	5	Cancel
	O Selected files	E 🕑 Deskto	op J.	Help
	<ul> <li>All files</li> </ul>	📄 😼 My	Computer Local Disk (C:)	
	C Fileer	±	LUCALDISK (C.)	-

- 3. Open the zip file and select the 'Extract' option on the folder toolbar, with the extract window displayed.
- 4.Select 'Desktop' from the folder/drives window.
- 5.Select the 'Extract' button.
- 6. A non-zipped folder should now be visible on the desktop.

Note: The programs contained within the files will **NOT** successfully run if the EXE file contained within the folder is activated whilst still located within the zip file.

The method of file extraction shown may vary dependant on the operating system your laptop is running.

The original downloaded Zip file is no longer necessary and can be deleted.

## Care points before starting software update procedure:

*Laptop:* Ensure that the TechCentre laptop will not go into standby mode in less than 5 minutes if no keystrokes have been detected. If the laptop is not normally connected to an external power supply whilst in the workshop then ensure its battery is sufficiently charged to carry out this procedure.

Continued.....



Bulletin number 2016/15 continued Page 3

*Vehicle:* If the vehicles battery condition is not known then it is recommended to connect the battery cables to an external charger whilst performing the update procedure.

#### **Updating Software**

1. Using the Lotus TechCentre laptop, connect the VCD yellow cable to the OBDII connector located beneath the driver side fascia at the outboard side of the footwell.



- 2. Close Lotus TechCentre application (if open).
- 3.Do not turn ignition on at this stage but make sure key is in to power the battery.
- 4.Open up the ECU program folder stored on the laptop and double click on "Prog\_T6\_ECU\_FIX.bat" file.
- 5.A command window will now appear displaying a 'Pass-Thru found' message. Select '1' on the keyboard for OmiPassThru and then press the enter button to confirm selection.

C:\WINDOWS\system32\cmd.exe
C:\Documents and Settings\ro35218\My Documents\Usef updates\] T6/ECUfix EFI_PROT T6/ECUfix CRP Device = Omitec Ltd OmiPassThru Function library = C:\Program Files\Omitec\J2534_04
Pass-Thru found:
1 - Omitec Ltd OmiPassThru
Select:

Continued.....

#### LOTUS CARS LIMITED



- 6.With the Pass-Through device now selected a new message 'Waiting Connection' is displayed.
- 7. The ignition should now be turned on to begin downloading the T6 ECU Fix program.

The status bar at the bottom of the screen will indicate the progress of the downloading procedure.

**WARNING:** Do not touch the keyboard or interrupt this procedure. Interrupting the download process will damage ECU!

Once the status bar reaches 100%, a 'successful download' message will be displayed in the command win-dow.

Wait for the instrument pack to stop displaying the "ECU Comms failure" message.

C:\WINDOWS\system32\cmd.exe
C:\Documents and Settings\ro35218\My Documents\Useful
updates\'Evora EFI\_PROT T6/ECU fix 3RP
Device = Omitec Ltd. - OmiPassThru
Function library = C:\Program Files\Omitec\J2534\_04\_04
Pass=Thru found:
1 - Omitec Ltd. - OmiPassThru
Select: 1
1 - Selected
Waiting Connection...

C:\Documents and Settings\ro35218\My Documents\Useful files calibration\Software
updates\\
CBP

Bulletin number 2016/15

continued Page 4

G:\Documents and Settings\ro35218\My Documents\Useful files calibration\Softwarv CRP Device = Onitec Ltd. - OniPassTheu Punction library = C:\Program Files\Onitec\J2534\_84\_84\OniPT32.DLL Pass-Thru found: 1 - Onitec Ltd. - OniPassThru Select: 1 1 - Selected Select: 1 Selected Select: 1 Selected Sele

8.Once this is achieved you can then turn off the ignition and press any key on the keyboard of the laptop to close the program.

NOTE: If after 1 minute the message is still present then switch off the ignition, wait for 5 seconds and then switch back on. The message on the right hand instrument panel display screen should disappear after 1 more minute.

IMPORTANT: The ECU is <u>NOT</u> blank in the condition and the above process is <u>NOT</u> suitable for blanking an ECU for recycling. Do not attempt the above process on an ECU which is able to communicate with the car or Techcentre or any car other than an Evora and Evora S.

The correct .crp program for the vehicle can now be reinstalled into the ECU using Lotus TechCentre.

Continued.....

LOTUS CARS LIMITED



Bulletin number 2016/15 continued Page 5

Reinstalling program

- With the yellow VCD cable to the vehicles ODBII connector still connected, open the Lotus TechCentre application.
- Manually type the VIN of the vehicle into the VIN search box.
- Search for the VIN number and select "EMS".
- When prompted, update the ECU software using the usual method.
- Re-enter the VIN number using the EMS guided routine function.
- Re-enter the EMS variant code using the guided routine function (this can be obtained from Lotus aftersales if required).

Note: Further information on how to use Lotus TechCentre can be found in the Lotus TechCentre Users Guide available to download from the Lotus within the >After sales>TechCentre & Production ECM Program Information category.

#### CHARGES:

A warranty claim for 0.3 hours labour may be submitted quoting Operation Code 13.02.01 - 07, 'A' code 27, 'B' code 37. Please quote Technical Service Bulletin number TSB 2016/15 in the text remarks section.

Ends.