



Service Engine Soon (MIL) – IHKA FC 801375 & 8013A3


This Service Information bulletin supersedes SI B12 27 15 dated November 2015

MODEL

I01 (i3 REx)	I12 (i8)	 F30 PHEV (330e)
--------------	----------	---

SITUATION

The Service Engine Soon light (MIL) is currently or intermittently illuminated in the instrument cluster and one or both of the fault codes below are stored in the Automatic Climate Control (IHKA).

-  801375 - Electric auxiliary heater (high voltage): Temporary fault detected after software reset

CAUSE

IHKA software or Electric Heater (EH).

PROCEDURE

- Is the vehicle already programmed with ISTA/P 3.57.1 (Target I-Level 15-11-502) or higher?
 - NO - Program vehicle with newest available software
 - YES - Continue to step 2
- Does the MIL illuminate again in combination with IHKA fault code 801375?
 - NO - The situation **has been resolved**, or if
 - YES - Replace the EH per REP “64 12 320 - Removing and installing/replacing electrical heating.”

PARTS INFORMATION

Part number	Description	Quantity
64 21 9 363 105	Flow heater electric	1

Bulk Materials

Part number	Description	Quantity

83 51 2 355 296	Coolant i3 (1 Liter concentrate)	With SA 4T9 – 1.9L
		Without SA 4T9 – 1.6L

Note: 1 liter of Coolant i3 concentrate at a 50/50 mixture provides 2 liters of coolant solution.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	64 21 05 15 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

And:

Labor Operation:	Labor Allowance:	Description:
61 25 910	Refer to KSD2	Recharging high-voltage battery unit (to high voltage charging unit)
And:		
61 00 730	Refer to KSD2	Programming / encoding control unit (s)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply(indicated in KSD2 as “Charging battery to EME”)

Or, for the:

i3 Only

Labor Operation:	Labor Allowance:	Description:
61 21 529	Refer to KSD2	Connect an approved battery charger/power supply(indicated in KSD2 as “i3) (luggage compartment service cap

		removed)
--	--	----------

And, if necessary

Procedure Step 2B

Labor Operation:	Labor Allowance:	Description:
64 12 821	Refer to KSD2	Replacing electric heating (after vehicle diagnosis)

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

And:

Sublet – Bulk Materials

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for the repair-related bulk materials (Please do not use the part number(s) for claim submission)
---------------	--	---

Sublet reimbursement calculation for claiming the “used quantities” of repair-related bulk materials (BMW part numbers) is at dealer net plus your center’s handling.

Enter this material cost in sublet and itemize the amount in the claim comment section.

[Copyright ©2016 BMW of North America, Inc.]