



SUBJECT

“Comfort Access Restricted” Check Control Message is Displayed

MODEL

F54 (Cooper Clubman, Cooper S Clubman)

F55 (Cooper Hardtop 4 Door, Cooper S Hardtop 4 Door)

F56 (Cooper Hardtop 2 Door, Cooper S Hardtop)

F57 (Cooper Convertible, Cooper S Convertible)

Vehicles produced November 1, 2013 to July 1, 2016

Vehicles with option code SA 322 (Comfort Access)

SITUATION

- “Comfort Access Restricted” CCM (Check Control Message) is permanently displayed.. The CCM ID: D0h.
- The comfort access is functioning correctly.
- No comfort access aerial fault codes stored in the BDC (Body Domain Controller).

CAUSE

Software error in the BDC

CORRECTION

Program the vehicle with ISTA/P 3.59.0 or higher, and I-Level

F54, F55, F56, and F57	F056-16-07-500 or higher
------------------------	--------------------------

PROCEDURE

In the event of a customer complaint, perform the following procedure.

NOTE: Replacing Parts will not rectify the problem.

1. Confirm the above situation, run diagnosis with ISTA/D and work through the corresponding test module reading check control history memory.
2. Program vehicle with ISTA/P 3.59.0 or higher (**available July 2016**).

If ISTA/P 3.59.0 is not yet available, the BDC must be reset using the following procedure:

- a. Perform vehicle test.
- b. Select the "BDC" control unit in the control unit tree.
- c. Select "Call control unit functions".
- d. Select the "Component activation" tab.
- e. Select "Reset control unit" and then "Activate component".

"Control unit reset was carried out" should appear on the right-hand side.

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software. For information on programming and coding with ISTA/P, refer to CenterNet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

Always connect a BMW approved battery charger / power supply(SI M04 08 09).

WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty or the MINI NEXT Certified Pre-Owned Limited Warranty.

Defect Code:	61 38 27 02 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply(indicated in KSD2 as "Charging battery")
And:		
61 00 730	Refer to KSD2	Programming / encoding control unit(s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

Vehicle Programming and Encoding

If a control module was working properly and it fails to program correctly or requires initialization, please claim this additional work with the applicable KSD2 labor operations under the defect code listed above.

The diagnosis and repair of vehicles “arriving” with failed control modules or stored faults which will cause them to fail during programming cannot be claimed under the defect code listed in this bulletin.

Other Repairs

If other eligible and covered work is performed “prior” to programming and coding the vehicle, claim this work with the applicable defect code and labor operations listed in KSD2.

[Copyright ©2016 BMW of North America, Inc.]