



N63R - Service Engine Soon Light with Oxygen Sensor faults Stored

MODEL

G12 (7 Series Sedan)	With the N63R engine produced to 3/22/2016
----------------------	--

SITUATION

The Service Engine Soon light is on (MIL) with either, or both, of the following oxygen sensor faults stored:

- 12A308 - Oxygen sensor after catalytic converter, signal: too slow from rich to lean
- 12A408 - Oxygen sensor 2 after catalytic converter, signal: too slow from rich to lean

CAUSE

DME software diagnostic function

CORRECTION

Reprogram the vehicle with revised DME software

PROCEDURE

1. Perform the recommended test plans using the latest version of ISTA.
2. Program the vehicle using ISTA/P 3.58.2 or higher.

New target integration level: **S15A 16-03-503** or higher

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW approved battery charger/power supply ([SI B04 23 10](#)).

For information on programming and coding with ISTA/P, refer to Centernet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

This repair is also covered by the terms of the Federal and/or State-specific Emissions Warranty (dependent on the vehicle's model year, state of registration and its inclusion on the "model-specific" list of covered components) that applies to the BMW model(s) listed.

The BMW Certified Pre-Owned Limited Warranty applies to BMW vehicles that have and are still

within the BMW Certified Pre-Owned coverage period, but beyond Emissions Warranty coverage that applies.

Defect Code:	10 42 31 59 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply(indicated in KSD2 as “Charging battery”)
And, as necessary:		
61 00 006	Work time (WT)	Performing vehicle diagnosis – test module
And:		
61 00 730	Refer to KSD2	Programming / encoding control unit(s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 61 00 006 is not considered a Main labor operation; however, it does require an individual punch time and an explanation on the repair order and in the claim comments.

Vehicle Programming and Coding

Control module failures that occur during programming:

- Please claim these consequential repairs under the defect code listed in this bulletin and use the applicable KSD2 labor operations.

Other Repairs

Control module failures that occur prior to programming:

- When covered under an applicable limited warranty, claim these repairs using the applicable defect code and labor operations in KSD2.

[Copyright ©2016 BMW of North America, Inc.]