



## F15, F30 PHEVs- Gear Selector Plausibility Faults

### MODEL

F15 PHEV (X5 xDrive 40e)	F30 PHEV (330e Sedan)	Vehicles with the integration level 16-03-505.
--------------------------	-----------------------	--

### SITUATION

The Check Control message “Drive: Stop carefully” (CCM-ID: 569) is displayed.

The following fault codes may be stored in the transmission EGS control module (GKEG3HY3):

- 44D663 – Position plausibility: Driver’s choice N/P from D/R not executed
- CF1701 – Gear selector switch interface, communication failure
- CF17A1 – Message missing: receiver EGS (A-CAN), transmitter selector switch (A-CAN)

### CAUSE

EGS software diagnostic function

### CORRECTION

Reprogram the vehicle with revised EGS software, when available.

### PROCEDURE

1. Perform short test and read EGS fault memory using the latest version of ISTA.
2. Program the vehicle using ISTA/P 3.59.1, or higher.

New target integration level: **16-07-500** or higher

(The ISTA/P 3.59.1 release is planned for mid June 2016). Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

**Always connect a BMW approved battery charger/power supply** ([SI B04 23 10](#)).

For information on programming and coding with ISTA/P, refer to Centernet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

### WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

<b>Defect Code:</b>	<b>24 00 32 66 00</b>	

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply(indicated in KSD2 as “Charging battery”)
And:		
61 00 730	Refer to KSD2	Programming / encoding control unit(s)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

### **Vehicle Programming and Coding**

Control module failures that occur during programming:

- Please claim these consequential repairs under the defect code listed in this bulletin and use the applicable KSD2 labor operations.

### **Other Repairs**

Control module failures that occur prior to programming:

- When covered under an applicable limited warranty, claim these repairs using the applicable defect code and labor operations in KSD2.

[ Copyright ©2016 BMW of North America, Inc. ]