



Unintentional Active ECO-PRO Bonus Miles Reset

MODEL

F01 (7 Series Sedan)	F02 (7 Series Sedan LWB)	F06 (6 Series Gran Coupe)	F07 (5 Series Gran Turismo)
F10 (5 Series Sedan)	F12 (6 Series Convertible)	F13 (6 Series Coupe)	

SITUATION

Fluctuations of fuel level (causing resistance changes in the level sensor) while vehicle is stationary, are interpreted as refueling. This causes active ECO PRO mode bonus range to reset.

CAUSE

Error in instrument cluster application.

CORRECTION

Program and code the vehicle with ISTA/P 3.58.0 (integration level F010-16-03-501) or higher.

PROCEDURE

Run diagnosis with ISTA and work through the corresponding test module.

Program and encode the vehicle with ISTA/P3.58.0 (integration level F010-16-03-501) or higher.

After programming to the afore-mentioned integration level, the ECO-PRO will continue to count correctly between vehicle refueling.

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software. For information on programming and coding with ISTA/P, refer to CenterNet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

Always connect a BMW approved battery charger / power supply ([SI B04 23 10](#)).

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	62 13 10 18 00		
Labor Operation:	Labor Allowance:	Description:	
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system –	

		checking faults)	
And:			
61 21 528	Refer to KSD2	Charging battery	
And			
61 00 730	Refer to KSD2	Programming / encoding control unit(s)	

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead. Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

Vehicle Programming and Coding

Control module failures that occur during programming:

- Please claim these consequential repairs under the defect code listed in this bulletin and use the applicable KSD2 labor operations.

Other Repairs

Control module failures that occur prior to programming:

- When covered under an applicable limited warranty, claim these repairs using the applicable defect code and labor operations in KSD2.

[Copyright ©2016 BMW of North America, Inc.]