



SLINGSHOT

Release Date: 05/18/2016
Expiration Date: 05/31/2017

TECHNICAL SERVICE BULLETIN

Slingshot

Bulletin Number: T-16-01
Model Year(s): 2016

☐ Safety Bulletin ☒ Service Bulletin ☐ Service Alert Fax ☐ Production Update Kit

Distribution: ☐ Owner / Principal ☐ Service Manager ☐ Sales Manager ☐ Parts Manager ☐ Technicians

This Service Bulletin is located at www.polarisdealers.com

-Confidential and Proprietary-

SUBJECT: 2016 Slingshot SL and LE models – Backup Camera Replacement

PURPOSE:

Polaris has determined that the backup camera in some 2016 Slingshot vehicles does not meet Polaris quality standards. Affected backup cameras exhibit higher levels of electrical interference, negatively impacting FM and AM radio reception. To resolve this concern, Polaris has completed validation of a revised backup camera that eliminates interference.

POTENTIALLY AFFECTED MODELS:

Model Year	Models	Vehicle Identification Number Range
2016	SL and LE MODELS	Enter the Vehicle Identification Number (VIN) into 'Unit Inquiry' to verify whether a vehicle is affected by this Service Bulletin.

WHAT YOUR DEALERSHIP SHOULD DO:

1. Review your dealership's inventory to locate affected models.
 - a. Use 'Unit Inquiry'.

OR

 - b. Login to the dealer website.
 - c. Locate the 'Service and Warranty' dropdown, click on STOP Site.
 - d. On the left hand side of the page, under 'STOP Site Links', click on 'Service Bulletins'.
 - e. Locate the T-16-01 link and click on the 'All VINs' link located on the right.
 - f. The 'All VINs' page will display all affected VINs within your dealership's inventory.
2. Perform the Backup Camera Replacement procedure outlined in this Service Bulletin on all affected units.
3. File a warranty claim following completion and attach a bulletin completion decal as shown on page 2 of this bulletin.

CUSTOMER NOTIFICATION:

Dealers are required to review their sales records and make arrangements with customers as needed. In addition to consumer units, dealers are required to correct any affected units in their inventory. Polaris will be mailing a notification letter to consumers affected by this Service Bulletin in the United States and Canada in early June as parts become available. Examples of the consumer letters can be found at the end of this Service Bulletin.

WARRANTY CLAIM INFORMATION:

A single group claim may be submitted listing the complete (17 digit) Vehicle Identification Number for machines with the same model number. File claim type: **SB (Service Bulletin)**. DO NOT PUT MORE THAN ONE MODEL NUMBER ON A CLAIM.

SERVICE BULLETIN #	T-16-01
CLAIM TYPE	SB (Service Bulletin)
LABOR ALLOWANCE	12 Minutes (0.2 Hours)
CLAIM PART NUMBERS	N/A – Auto Process Bulletin

PARTS INFORMATION:

PART NUMBER / DESCRIPTION	7170107 (QTY.1) – Service Bulletin Completion Decal 4016539 (QTY.1) – CAMERA-REAR,LINES
PARTS AVAILABILITY	Available to order. Limited quantities available before 6/10/2016.
DIRECT-SHIP FROM POLARIS?	No
TO BE ORDERED BY DEALER?	Yes – Order Bulletin Completion decals through normal parts channels

PARTS RETURN OR DISPOSAL INFORMATION:

North American Dealers: Once the warranty claim for each unit has processed, please review the “Check Returned Parts List” on your dealer website to determine whether or not Polaris has asked for the part(s) to be returned. If the part(s) were not identified as needing to be returned to Polaris, please dispose of the part(s) properly.

International Dealers & Distributors: Under no circumstances shall the part(s) removed in this repair be re-used, sold, or re-purposed for another application. It is your dealership / distributorship’s responsibility to make sure every part replaced is taken out of circulation and disposed of properly.

WARRANTY COVERAGE PERIOD:

Warranty coverage for Service Bulletin T-16-01 begins on May 18, 2016 and will expire on May 31, 2017. All affected vehicles are covered during the campaign period. After the expiration date, only wholegood stock (WS) and vehicles within the warranty period (including the ESC period) will receive warranty coverage. Vehicles outside the factory warranty or ESC period will not receive warranty coverage after the expiration date.


SERVICE BULLETIN COMPLETION DECAL:

A Service Bulletin Completion Decal (PN 7170107) must be completed for this bulletin repair. Place the decal on the left side frame tube, near the brake master cylinder (as shown). If you require more decals, order them through normal Polaris parts ordering channels.

Sincerely,




Doug Koch
Technical Service and Warranty Manager



BACKUP CAMERA REPLACEMENT

1. Carefully lift up on the backup camera mount to remove from the vehicle.



2. Gently pull on backup camera wire until the connector becomes visible. Disconnect the backup camera from the harness.



3. Press the camera out of the mount to remove.


4. Connect the new camera to the harness.

5. Align the tab in the backup camera with the mount tab.

6. Secure the camera into the mount.

7. Install camera and mount to vehicle engaging retention tabs.

8. Test vehicle to verify normal operation of the radio and backup camera.





Slingshot Division
Polaris Industries Inc.
P.O. Box 47700
Medina, MN 55340-9960

VIN

FIRST NAME LAST NAME
ADDRESS
CITY, ST ZIP

Dear Slingshot Owner,

Thank you for purchasing a 2016 Polaris Slingshot. Our top priority at Polaris is customer satisfaction, and we know satisfaction is driven by product quality. Recently we identified a quality concern that affects a limited number of 2016 Slingshot SL and SL LE models. Our records indicate that you have purchased a potentially affected vehicle. Please take a moment to review this letter.

The reason for this Technical Service Bulletin:

Polaris has determined that the backup camera in some 2016 Slingshot vehicles does not meet our quality standards. Affected backup cameras exhibit higher levels of electrical interference, negatively impacting FM and AM radio reception.

What Polaris and your dealer will do:

On May 18, 2016 Polaris released Technical Service Bulletin T-16-01 to all Slingshot dealers, with instructions to install a revised backup camera to address the radio reception concern. Revised backup cameras are available and repairs will be made by an authorized Slingshot dealer at no cost to you. The actual repair should take under fifteen minutes to perform; however, it may take longer due to service scheduling requirements.

What you should do:

Contact your authorized Slingshot dealer to schedule an appointment to have the bulletin repairs performed. Do not attempt repairs yourself. Repairs must be completed by an authorized Slingshot dealer.

If you have questions or if you need more information:

While your Slingshot dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, or if you need assistance finding a Slingshot dealer, please visit the Slingshot web site at <http://www.polaris.com/en-us/slingshot> or contact our Slingshot Consumer Service Department by calling 1-855-863-2284.

We apologize for this inconvenience and assure you that we are committed to quality and building the best vehicles in the world.

Sincerely,

Polaris On-Road Vehicles