

SERVICE CAMPAIGN BULLETIN

TITLE:	Vehicle Software Update to Platform 4.2
CAMPAIGN REFERENCE	03V
DOCUMENT NUMBER:	13 M 001
AFFECTED VEHICLES:	Sports Series
SITUATION:	<p>Quality Engineering at McLaren Automotive have released a new software platform for the Sports Series</p> <p>The customer benefits of this software are:</p> <ul style="list-style-type: none">•Improve functionality of nose lift operation•Improve HVAC temperature control•Improve AIS IRIS to prevent system freeze•Introduction of Gen2 12v battery software
PROCEDURE:	<p>It is necessary to update the software and replace the TPMS module on all vehicles within your Aftersales car parc, both when carrying out Pre-Delivery Inspections (PDI) and at the next service centre visit.</p>

Module	New software part numbers
Front Wiper Motor (FWM)	13A6451CP.02 LHD 13A6452CP.02 RHD
Intelligent Battery Sensor (IBS)	13M1080CP.12
Instrument Cluster (IC)	13M1646CP.04
Body Controller (BC)	13M1276CP.06
Security Body Controller (SBC)	13M1275CP.07
Switch Control Unit Gateway (SCUG)	13M0487CP.04
Door Module Left (DML)	13M0778CP.04
Door Module Right (DMR)	13M0779CP.04
Heating Ventilation and Air-Conditioning (HVAC)	13M0489CP.08
Electronic Stability Program (ESP)	13M0932CP.08
Seat Control Module Left (SCML)	13N2632CP.10
Seat Control Module Right (SCMR)	13N2632CP.10
Powertrain Chassis Control Unit (PCCU)	13M0829CP.07
Engine Control Module (ECM)	13M1465CP.03 570S European/ROW 13M1340CP.03 570S Federal 13M1470CP.03 540C European/ROW 13M1469CP.03 540C Federal
Head Unit (HU)	13MA053CP.01 Europe 13MA054CP.01 ROW 13MA055CP.01 China 13MA056CP.01 Japan

Removal:

1. CA-RM-01A001-00-001 - Secure/Lift vehicle on platform .

Care Point: Right hand wheel arch liner only.

2. CA-RM-04B005-01-001 - Remove/Install wheel - Rear .
3. CA-RM-03A076-02-001 - Remove/Install wheel arch liner - Rear .
4. CA-RM-07M002-12-001 - Remove/Install control unit/antenna - Tyre Pressure Monitoring System (TPMS)

Installation:

5. Install the components in reverse order.
6. Remove the battery access cover to allow access to the 12 volt battery.

Requirements:

Care Point: In order to avoid personal injury and damage to the vehicle, do not connect the positive terminal (+) of the charger to the negative terminal (-). Ensure that the connections are secure. Do not place any metal objects near the battery when charging and do not place the Deutronic battery charger directly onto the battery unit.


7. Connect Deutronic battery charger to the 12V battery and leave it connected during software reprogramming procedure.
8. Connect the McLaren Diagnostic System (MDS) to the vehicle.

Care Point: If the VCI is connected to the MDS via the USB cable please ensure the wireless interface is disabled in the VCI Manager.

Care Point: Both the driver and passenger windows must be in the fully open position during software reprogramming procedure.


Care Point: All software downloads require the vehicle to be in ignition state 5.

Care Point: The key must be positioned in the driver's seat front pocket (1).



TPMS configuration

9. Select TPMS (1), then Sequences (2), select TPMS Configuration (3). Proceed by selecting the arrow button (4).




10. Select Program VIN (5). Proceed by selecting the arrow button (4).

FWM Software Update:

Care Point: *FWM_Base* may be displayed in italics.


11. Select FWM (1), then Reprogramming (2), the correct software level for the vehicle will be displayed (3). Proceed to the software download by selecting the arrow button (4).



IBS Software Update:

Care Point: *IBS_Base* may be displayed in italics.

12. Select IBS (1), then Reprogramming (2), the software level 13M1080CP.12 will be displayed (3). Proceed to the software download by selecting the arrow button (4).




IC Software Update:

Care Point: Ensure that you have read 13S001 Instrument Cluster (IC) reprogramming via USB method .

Care Point: During the IC programming phase a "Post Condition Failed" message will illuminate, please ignore the message as it does not affect the programming of the module.


Care Point: The IC will need to be reprogrammed twice during this update.

13. Select IC (1), then Reprogramming (2), select software level 13M1642CP.02 (3). Proceed to the software download by selecting the arrow button (4).




14. In the next screen you will be asked to select between CAN or USB.


15. Select USB to reprogram the IC via USB to proceed (5).



16. Once reprogramming has completed Programming failed will be displayed (6).




17. Select Reprogramming (7), select software level 13M1646CP.04 (8). Proceed to the software download by selecting the arrow button (9).




18. Repeat steps 14 to 15 and Programming failed will be displayed again as mentioned at step 16.

Post Reprogramming requirements:


19. IC software level confirmation needs to be performed. Confirm the IC software levels are the same as the screenshot below (10). If they are the same proceed to step 20. If they are incorrect raise a technical request with IC software level information.



20. Once the reprogramming has been completed successfully the wireless function must be enabled once again if you are using the VCI wireless.
21. Disconnect all the cables from the vehicle and keep them in a safe place.
22. Install components in reverse order and allow vehicle to sleep for 15 minutes before proceeding to next step.
23. Select Coding (11), followed by the arrow key (12) to write the new IC coding string.




24. Select Sequences (13), select Set configuration defaults (14) then select the arrow button to proceed (15).
25. Select Align Vehicle Configuration (16), followed by the arrow key (15).




BC Software Update:


26. Select BC (1), then Reprogramming (2), the software level 13M1276CP.06 will be displayed (3). Proceed to the software download by selecting the arrow button (4).



27. Select Sequences (5), then Programme VIN (6), then select the arrow button to proceed (7).




28. Select Align Vehicle Configuration (8), followed by the arrow key (9).



SBC Software Update:


29. Select SBC (1), then Reprogramming (2), the software level 13M1275CP.07 will be displayed (3). Proceed to the software download by selecting the arrow button (4).



30. When the software download has been successfully completed, programming will force a sleep cycle to occur.


31. After one minute, press the unlock, lock and the unlock button on the key and then establish the vehicle into ignition state 5 before following the next steps.

32. Select Sequences (5), then Programme VIN (6) then select the arrow button to proceed (7). The programme VIN procedure will force a sleep cycle to occur after the programming is complete.



33. Press the unlock button on the key and then establish the vehicle into ignition state 5 before following the next steps.


34. Select Align Vehicle Configuration (8), followed by the arrow key (9).




35. Press the unlock button on the key and then establish the vehicle into ignition state 5 before following the next steps.

SCUG Software Update:


36. Select SCUG (1), then Reprogramming (2), the software level 13M0487CP.04 will be displayed (3). Proceed to the software download by selecting the arrow button (4).



37. Select Coding (5), then Write_code_string (6), then select the arrow button to proceed.




38. Select Sequences (5), select Steering Column Calibration (6) then select the arrow button to proceed (7).




DML Software Update:

39. Select DML (1), then Reprogramming (2), the software level 13M0778CP.04 will be displayed (3). Proceed to the software download by selecting the arrow button (4).




40. Select Sequences (5), select Align Vehicle Configuration (6), followed by the arrow key (7).

41. Select Window Calibration (8), followed again by the arrow key (7).




DMR Software Update:

42. Select DMR (1), then Reprogramming (2), the software level 13M0779CP.04 will be displayed (3). Proceed to the software download by selecting the arrow button (4).




43. Select Sequences (5), select Align Vehicle Configuration (6), followed by the arrow key (7).
44. Select Window Calibration (8), followed again by the arrow key (7).




HVAC Software Update:

45. Select HVAC (1) then Reprogramming (2), the software level 13M0489CP.08 will be displayed (3). Proceed to the software download by selecting the arrow button (4).



ESP Software Update:

46. Select ESP (1), then Reprogramming (2), the software level 13M0932CP.08 will be displayed (3). Proceed to the software download by selecting the arrow button (4).




Care Point:- If either seat modules does not flash successfully do not attempt to reflash again, raise a technical request.


SCML Software Update:

Care Point: Both doors must be closed and the seat must not be operated during reprogramming, failure to do this will cause the seat to no longer function.

47. Select SCML (1), then Reprogramming (2), the software level 13N2632CP.10 will be displayed (3). Proceed to the software download by selecting the arrow button (4).




48. Select Sequences (5), select Seat Calibration (6), followed by the arrow key (7).




SCMR Software Update:

Care Point:- Both doors must be closed and the seat must not be operated during reprogramming, failure to do this will cause the seat to no longer function.

49. Select SCMR (1), then Reprogramming (2), the software level 13N2632CP.10 will be displayed (3). Proceed to the software download by selecting the arrow button (4).



50. Select Sequences (5), select Seat Calibration (6), followed by the arrow key (7).




51. Switch the ignition off and place the vehicle into a sleep mode, and then establish the vehicle back into ignition state 5.

52. Perform a DTC read and clear from all modules.

PCCU Software Update:


Care Point: During the reprogramming of the PCCU the system may state preconditions or post conditions failed. These are erroneous messages and can be ignored. Only a programming failed message should be noted as a legitimate failure.

53. Select PCCU (1), then Reprogramming (2), the software level 13M0829CP.07 will be displayed (3). Proceed to the software download by selecting the arrow button (4).




54. Cycle the ignition (off on off on) and wait for 30 seconds. Place the vehicle into a sleep mode, and then establish the vehicle back into ignition state 5. Clear any DTC's before continuing on with the procedure.


55. Select PCCU (5), then Sequences (6), select Align Vehicle Configuration (7), followed by the arrow key (8).



56. Select Programme VIN (9), followed by the arrow key (10).




57. Select Dual Clutch Calibration (11), followed by the arrow key (12) and the clutch calibration will be performed.



58. Allow vehicle to sleep fully, then switch the ignition back on and perform a DTC read and clear for all modules.

ECM Software Update:

59. Select ECM (1), then Reprogramming (2), the software variant applicable to your market will be displayed (3). Proceed to the software download by selecting the arrow button (4).




60. Cycle the ignition (off on off on) and wait for 30 seconds.

61. Press the stop/start button with the brake pedal depressed to start the engine and allow it to idle until fully warm.

Care Point: Vehicles installed with air conditioning must be switched on and the engine coolant temperature must be above 80°C before proceeding with the camshaft adaption procedure.

62. Select ECM (5), then Actual Values (6), select the following values as per the screenshot below (7), then select the play button to access the required data screen.

63. The inlet camshaft values should be between 9 and 12 and exhaust values should be between -9 and -12 both values will fluctuate slightly. If all values are correct no further action is required proceed to step 65. If any values are incorrect proceed to step 64 to carry out the camshaft adaption.




64. Switch the engine off, wait 30 seconds, restart the engine and recheck the values. Repeat this procedure until the target values are achieved.

Care point: The fuel level must be above 1/4 before you proceed to the Diagnostic Module Leakage Test (DMTL).

Care point: The DMTL test can take up to eight minutes to complete the 20 thou and 40 thou leak test

65. Select Sequences (8), then DMTL Diagnostic Module Leakage Test (9), followed by the arrow button to proceed (10).



66. Perform a DTC read and clear from all modules.

67. End the current MDS session to allow session feedback to be sent and stored at McLaren.

IRIS AIS Application Software:



Care Point: The Application Software will be supplied via USB to dealers.

Care Point: Do not turn off the engine or change the ignition state during the update process unless stated within this update procedure.



- 68. Switch the ignition ON to ignition state 5 and start the engine.
- 69. Make a note of the options displayed on the Home Screen as this information will be required to configure the head unit.
- 70. Insert the USB drive with the application software into the USB socket (1).




- 71. Once the USB has been inserted, the system should provide a message stating a USB device has been detected.
- 72. Press the Settings hard button on the IRIS console.
- 73. Select About (2) and then Update Product (3).




74. On the following screen select Update by USB Stick (4). A pop up message will be displayed. Press OK (5) to start the loading operation.





75. The following screen will be displayed (6) and the system will reboot.



76. After the system has rebooted it will search for and check the update file (7). Once the installation has finished the following screen will be displayed (8) and the system will reboot.





77. Following the reboot the system will start to update the individual system components (9), (10). During the update the system may reboot multiple times. This is normal, **do not attempt a manual reset**.



Care Point: In case the system should get stuck on the update screen if one of the component updates has failed, press and hold the home button for 45s to force the system to reboot.

78. Once all components have been updated and the system has fully rebooted, press the Settings hard button on the IRIS console.

79. Select About (11) and then select Versions (12).




80. Confirm that the McLaren Software Part Number matches the Part Number listed in Table at Page 2 of this document.

81. Press the Home button on the IRIS console to return to the Home screen and remove the USB drive.

Care Point: For vehicles where the Learn Vehicle Model process has been completed previously the option will not be available on the Home screen. In this case go to step 83.


82. Select Learn Vehicle Model (13) from the Home Screen. The system will perform a configuration update and reboot. Wait until the system has fully booted to the Home screen before proceeding to the next step.




Care Point: The VCI must be connected to the MDS with the USB cable to perform the next steps.

83. Select HU_02 (1), then select Sequences (2), select Align Vehicle Configuration (3), followed by the arrow key (4).


84. Select Programme VIN (5), followed by the arrow key (4).




85. Select Head Unit Configuration (6), followed by the arrow key (7).



86. The following screen will appear, select OK (8).




87. Select the relevant country followed by OK (9)




Care Point: The following screen may not appear due to your market has no applicable options, proceed to step 89.

88. Select the relevant radio frequency option, followed by OK (10).




89. Is rear view camera fitted, select Yes or No (11).




Care Point: The screenshot below may not appear due to database stored on the MDS may contain the VIN number.

90. Proceed and select No (12).




91. Operation successful will be displayed. Select the back arrow to exit the sequence (13).




Care Point: Performing Factory Data Reset will delete the stored radio stations and paired phones.

92. Press the Settings hard button on the IRIS console.

93. Select Advanced Settings (14) and then Privacy (15) in order to access the Factory Data Reset.



94. Select Factory Data Reset (16) followed by Reset (17) and then Erase Everything (18).




95. The system will reboot. The Factory Data Reset will be completed once the system has returned to the Standby Screen.


96. Wait until the system has fully rebooted, then switch the engine off and ignition back on.

Adaptions Requirements:

97. Select ECM (1), then Sequences (2), then Clear Misfire adaptations (3), followed by the arrow button (4) to proceed.



98. Select Actual Values (5), select the following values as per the screenshot below (6), then select the play button to access the required data screen.



99. Misfire adaptations are performed whilst the car is driven with the gearbox set to manual mode and with the A/C off. Perform eleven successive fuel cuts from above 4000rpm for a 5 second duration (a fuel cut off will occur when the accelerator pedal is fully released).

100. Once the Fuel off Adaption Counter reaches 11, the Fuel off Adaption Finished Counter will display 1; the misfire adaptations have been learned. The Fuel off Adaption Counter will display Zero and then start to count again when further fuel cut offs occur, this is correct operation and no further action is required.

101. Perform a DTC read and clear from all modules.

Please contact your Regional Aftersales Manager should you have any questions relating to the information contained in this bulletin.

Warranty Information: Claim an additional 0.50 hours as an additional cost.

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
Software Platform Update to 4.2	CGMB0302A33I4A07	2.45 hours

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
TPMS ECU/ANTENNA 433MHZ	13M1506CP	1	Unipart
TPMS ECU/ANTENNA 315MHZ	13M1507CP	1	Unipart

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren Bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers. The information contained in McLaren bulletins are for internal use only by McLaren Authorised Retailers and must not be published on external website or social media forums etc.