


SERVICE CAMPAIGN BULLETIN

TITLE:	Front Subframe Bolt Replacement
CAMPAIGN REFERENCE	044
DOCUMENT NUMBER:	11 A 065
AFFECTED VEHICLES:	Super Series
SITUATION:	Quality Engineering at McLaren Automotive require the front subframe bolts to be replaced due to the bolt 00RA534 coating being incorrect and causing degradation in the earthing circuit over time.
PROCEDURE:	This rework must be completed on all vehicles at PDI or before the handover of a new vehicle to a customer.

Removal:

1. Please refer to CA-RM-01A001-00-001 - Secure/Lift vehicle on platform.
2. Locate the four rear mounting bolts for the front subframe (1).



3. Remove one bolt and install new bolt 11A9786CP and torque M10 x 85 to 50 Nm.
4. Repeat step 3 with the three remaining bolts.
5. Then torque all four bolts to 70Nm.

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
Front Subframe Bolt Replacement	A0A10213A16B9901	0.30 hours

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
Bolt M10 X 85	11A9786CP	4	Unipart

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren Bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers. The information contained in McLaren bulletins are for internal use only by McLaren Authorised Retailers and must not be published on external website or social media forums etc.