# **Service Bulletin**

Mazda North American Operations Irvine, CA 92618-2922



© 2016 Mazda Motor of America, Inc.

Subject: UNUSUAL ENGINE NOISE AFTER A COLD ENGINE START	Bulletin No: 01-018/16
	Last Issued: 10/25/2016

#### **BULLETIN NOTE**

This bulletin supersedes the previously issued bulletin(s) listed below: The changes are noted in Red beside the change bars.

Previously issued TSBs:	Date issued:	
01-006/13	02/13/2013	

#### APPLICABLE MODEL(S)/VINS

I	2016-2017 Mazda2	2014-2017 Mazda6	2013- <mark>2016</mark> CX-5	2016-2017 MX-5
I	2014-2017 Mazda3	2016-2017 CX-3	2016 CX-9	

#### DESCRIPTION

Some customers may complain about an unusual noise coming from the engine compartment for about 20 seconds after a cold engine start. This noise is a normal engine operation for improved exhaust gas emissions. The noise does not indicate a malfunction.

#### ACCELERATED WARM-UP SYSTEM (AWS)

All SKYACTIV-G engines adopt AWS to reduce exhaust gas emissions immediately after a cold engine start. AWS increases the engine idling speed and retards the ignition timing for about 20 seconds after the cold engine start to quickly warm up the catalytic converter. The customer may identify the engine sound during the AWS operation as a unusual noise.

#### **AWS OPERATION**

- a. Engine coolant temperature of less than 113F (145C) at engine start.
  - b. At idle (accelerator pedal off) with transmission in P, N, or D.

Page 1 of 2

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

#### **AWS CONTROL**

- a. Ignition timing is retarded about 20 degrees.
  - b. Engine speed is increased.

AWS burns fuel inside the exhaust manifold (A) to quickly warm up the catalytic convertor. The customer may identify the burning sound as an unusual noise.

### AWS CANCELATION

AWS is canceled when the vehicle is driven.

## AWS IDENTIFICATION

- a. Customer states the noise is about 20 seconds after a cold engine start.
- b. There is no leakage from the exhaust system.

