

SERVICE BULLETIN

Classification: EC12-010f Reference:

ITB12-026f

COPYRIGHT© NISSAN NORTH AMERICA, INC. Date:

March 15, 2016

MIL ON WITH DTC P0106 STORED

This bulletin has been amended to edit the part numbers in Table A on page 5 and remove 2010 G37 Convertible from Applied vehicles. No other changes have been made. Please discard all previous versions of this bulletin.

APPLIED VEHICLES:

2010-2012 FX50 (S51) 2010-2012 G37 Sedan (V36) 2010-2012 G37 Coupe (CV36) 2011-2012 G37 Convertible (HV36) 2011-2012 M37 and M56 (Y51) 2011-2012 QX56 (Z62)

IF YOU CONFIRM:

An APPLIED VEHICLE has the MIL ON with DTC P0106 (Manifold Absolute Pressure [MAP] circuit range/performance) stored in the ECM.

ACTION:

- 1. Refer to step 6 in the **SERVICE PROCEDURE** to confirm this bulletin applies to the vehicle you are working on.
- 2. If this bulletin applies, reprogram the ECM with CONSULT-III plus ONLY.

IMPORTANT: The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire **SERVICE PROCEDURE** as it contains information that is essential to successfully completing this repair.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

NOTE:

- Most instructions for reprogramming with CONSULT-III plus (C-III plus) are displayed on the CONSULT PC screen.
- If you are not familiar with the reprogramming procedure, click here. This will link you to the "CONSULT- III plus (C-III plus) ECM Reprogramming" general procedure.
- Take the vehicle for a 10 minute drive in order to meet the following Idle Air Volume Learn (IAVL) conditions:
 - Engine coolant temperature: 70 105°C (158 - 221°F)
 - ➤ Battery voltage: More than 12.9V (At idle)
 - Transmission: Warmed up



Figure A

• After reprogramming is complete, you will be required to perform Throttle Valve Closed Position, Idle Air Volume Learn, Accelerator Closed Position, and DTC erase.


CAUTION:

- Connect the GR8 to the vehicle 12 volt battery and set to ECM power supply mode. If the vehicle battery voltage drops below <u>12.0V or above 15.5V</u> during reprogramming, <u>the ECM may be damaged</u>.
- Be sure to turn OFF all vehicle electrical loads. If a vehicle electrical load remains ON, <u>the ECM may be damaged</u>.
- Be sure to connect the AC Adapter. If the CONSULT PC battery voltage drops during reprogramming, the process will be interrupted and <u>the ECM may be damaged</u>.
- Turn off all external Bluetooth[®] devices (e.g., cell phones, printers, etc.) within range of the CONSULT PC and the VI. If Bluetooth[®] signal waves are within range of the CONSULT PC during reprogramming, reprogramming may be interrupted and <u>the ECM may be damaged</u>.

- 1. Connect the CONSULT PC to the vehicle to begin the reprogramming procedure.
- 2 Start C-III plus.

NOTE: This is a <u>C-III plus</u> ONLY reprogram.

- 3. Wait for the plus VI to be recognized / connected.
 - The serial number will display when the plus VI is recognized / connected.
- 4. Select Re/programming, Configuration.



5. Follow the on-screen instructions and navigate the C-III plus to the screen shown in Figure 2 on the next page.

- 6. When you get to the screen shown in Figure 2, confirm this bulletin applies as follows.
 - A. Find the ECM Part Number and write it on the repair order.

NOTE: This is the <u>current</u> ECM Part Number (P/N).

CONSULT-III plus Ver VIN	Vehicle :	Country : U.S.A.	
Back Home Print Screen Capture	Measurement Mode	🚓 🏋 🗙 🖿 📄	\times
Re/programming, Configuration Opera	tion Selection Save ECU Data		717
Save ECU Data			
Touch "Save" to save operation log and th Operation log helps to restart next operation after operation has completely finished.			0
File Label	>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>		
Operation	REPROGRAMMING		
System 6A: <u>Current</u> E			
Part Number	23710		
Vehicle	******		
VIN	xxxxxxxxxxxxxxxxxxxxxxxxx		
Date	11/1/201× 1:22:16 AM	1 Save	

Figure 2

- B. Compare the P/N you wrote down to the numbers in the **Current ECM Part Number** column in **Table A** on the next two pages.
 - If there is a <u>match</u>, this bulletin <u>applies</u>. Continue with the reprogramming procedure.
 - If there is <u>not a match</u>, this bulletin <u>does not apply</u>. Close C-III plus and refer to ASIST for further diagnostic information.

Table A

Model	Current ECM Part Number: 23710-	
2010-2011 FX50	1WX0A, 1WX0B, 1WX1A, 1WX1B, 1WX2A, 1WX2B, 1WX3A, 1WX3B 3FY4A, 3FY4B, 3FY5A, 3FY5B, 3FY8A, 3FY9A 1WX0C, 1WX1C, 1WX2C, 1WX3C 1WX0D, 1WX1D, 1WX2D, 1WX3D	
2012 FX50	3EU0A, 3EU1A	
2010 G37 Sedan	1MW0A, 1MW1A, 1MW2A, 1MW3A, 1MW6A, 1MW7A 1MW0B, 1MW1B, 1MW2B, 1MW3B, 1MW6B, 1MW7B 1MW0C, 1MW1C, 1MW2C, 1MW3C, 1MW6C, 1MW7C 1MW0D, 1MW1D, 1MW2D, 1MW3D, 1MW6D, 1MW7D 1NS0A, 1NS1A, 1NS2A, 1NS3A, 1NS4A, 1NS5A, 1NS6A, 1NS7A 1NS0B, 1NS1B, 1NS2B, 1NS3B, 1NS4B, 1NS5B, 1NS6B, 1NS7B 1NS0C, 1NS1C, 1NS2C, 1NS3C, 1NS4C, 1NS5C, 1NS6C, 1NS7C 1NS0D, 1NS1D, 1NS2D, 1NS3D, 1NS4D, 1NS5D, 1NS6D, 1NS7D 1NS0E, 1NS1E, 1NS2E, 1NS3E, 1NS4E, 1NS5E, 1NS6E, 1NS7E 3WP0A. 3WP1A 3WP0B, 3WP1B	
2010 G37 Coupe	1NG0A, 1NG1A, 1NG2A, 1NG3A, 1NG5A, 1NG6A, 1NG7A, 1NG8A 1NG0B, 1NG1B, 1NG2B, 1NG3B, 1NG5B, 1NG6B, 1NG7B, 1NG8B 1NG0C, 1NG1C, 1NG2C, 1NG3C, 1NG5C, 1NG6C, 1NG7C, 1NG8C 1NG0D, 1NG1D, 1NG2D, 1NG3D, 1NG5D, 1NG6D, 1NG7D, 1NG8D 1NG0E, 1NG1E, 1NG2E, 1NG3E, 1NG5E, 1NG6E, 1NG7E, 1NG8E 1PX0A, 1PX1A, 1PX2A, 1PX3A, 1PX7A, 1PX8A 1PX0B, 1PX1B, 1PX2B, 1PX3B, 1PX7B, 1PX8B 1PX0C, 1PX1C, 1PX2C, 1PX3C, 1PX7C, 1PX8C 1PX0D, 1PX1D, 1PX2D, 1PX3D, 1PX7D, 1PX8D 3WP3A, 3WP3B 3WP2A, 3WP2B	
2011 G37 Sedan	1NX0A, 1NX1A, 1NX2A, 1NX3A, 1NX4A, 1NX6A, 1NX7A 1NX0B, 1NX1B, 1NX2B, 1NX3B, 1NX4B, 1NX6B, 1NX7B 1NX1C, 1NX2C, 1NX3C, 1NX6C, 1NX7C 1NX0D	
2011 G37 Coupe	1A32B, 1A32H 1A35B, 1A36B 1A36A 1VU0A, 1VU1A, 1VU2A, 1VU3A, 1VU4A, 1VU5A, 1VU6A, 1VU7A 1VU0B, 1VU1B, 1VU2B, 1VU3B, 1VU4B, 1VU5B, 1VU6B, 1VU7B 1VU1C, 1VU3C, 1VU6C, 1VU7C 1VU2D	

Model	Current ECM Part Number: 23710-		
	1NY0A, 1NY1A, 1NY2A, 1NY3A, 1NY4A, 1NY5A		
2011 G37 Convertible	1NY0B, 1NY1B, 1NY2B, 1NY3B, 1NY4B, 1NY5B		
	1NY1C, 1NY2C, 1NY3C		
2012 G37 Sedan	EY00A, EY01A, EY02A, EY03A, EY04A, EY05A, EY06A EY00B, EY01B, EY02B, EY03B, EY04B, EY05B, EY06B		
	1A34C, 1A34D		
	1A340, 1A340 1A37A, 1A37B		
2012 G37 Coupe	1JT0A, 1JT1A, 1JT2A, 1JT3A, 1JT4A, 1JT5A, 1JT6A		
	1JT0B, 1JT1B, 1JT2B, 1JT3B, 1JT4B, 1JT5B, 1JT6B		
0010 007 0 111	1VZ0A, 1VZ1A, 1VZ2A, 1VZ3A, 1VZ4A		
2012 G37 Convertible	1VZ0B, 1VZ1B, 1VZ2B, 1VZ3B, 1VZ4B		
	1MA0A, 1MA1A, 1MA2A, 1MA3A, 1MA4A		
	1MA5A, 1MA6A, 1MA7A, 1MA8A, 1MA9A		
	1MA0B, 1MA1B, 1MA2B, 1MA3B, 1MA4B, 1MA5B		
2011 M37	1MA0C, 1MA1C, 1MA2C, 1MA3C, 1MA4C, 1MA5C		
	1MA0D, 1MA1D, 1MA2D, 1MA3D, 1MA4D, 1MA5D		
	1MA1E, 1MA2E, 1MA3E, 1MA4E, 1MA5E		
	1MB7A, 1MB8A, 1MB9A		
2012 M27	1MV0A, 1MV1A, 1MV2A, 1MV3A, 1MV4A, 1MV5A		
2012 M37	MV0B, 1MV1B, 1MV2B, 1MV3B, 1MV4B, 1MV5B 1MV0C, 1MV1C, 1MV2C, 1MV3C, 1MV4C, 1MV5C		
	1MX0A, 1MX1A, 1MX2A, 1MX3A, 1MX4A, 1MX5A		
	1MX0B, 1MX1B, 1MX2B, 1MX3B, 1MX4B, 1MX5B		
	1MX0C, 1MX1C, 1MX2C, 1MX3C, 1MX4C, 1MX5C		
	1MX0D, 1MX1D, 1MX2D, 1MX3D, 1MX4D, 1MX5D		
2011 M56	1MX0E, 1MX1E, 1MX2E, 1MX3E, 1MX4E, 1MX5E		
	1MP4A, 1MP5A, 1MP6A, 1MP7A, 1MP8A, 1MP9A		
	1MP4B, 1MP5B, 1MP6B, 1MP7B, 1MP8B, 1MP9B		
	1MP4C, 1MP5C, 1MP6C, 1MP7C, 1MP8C, 1MP9C		
	1MP4D, 1MP5D, 1MP6D, 1MP7D, 1MP8D, 1MP9D		
	1MU0A, 1MU1A, 1MU2A, 1MU3A, 1MU4A, 1MU5A		
	1MU0B, 1MU1B, 1MU2B, 1MU3B, 1MU4B, 1MU5B		
2012 M56	1MU0C, 1MU1C, 1MU2C, 1MU3C, 1MU4C, 1MU5C 1MU0D, 1MU1D, 1MU2D, 1MU3D, 1MU4D, 1MU5D		
2012 100	1MU0E, 1MU1E, 1MU2E, 1MU3E, 1MU4E, 1MU5E		
	1MK0A, 1MK1A, 1MK2A, 1MK3A, 1MK4A, 1MK5A		
	1MK0B, 1MK1B, 1MK2B, 1MK3B, 1MK4B, 1MK5B		
	1LA3B, 1LA4B, 1LA5B, 1LA6B		
	1LA3C, 1LA4C, 1LA5C, 1LA6C		
	1LA3D, 1LA4D, 1LA5D, 1LA6D		
2011 QX56	1LA3E, 1LA4E, 1LA5E, 1LA6E		
	1LS0A, 1LS1A, 1LS2A, 1LS3A		
	1LS0B, 1LS1B, 1LS2B, 1LS3B		
	1LS0C, 1LS1C, 1LS2C, 1LS3C		
	1ZS0A, 1ZS1A, 1ZS2A, 1ZS3A 1ZS0B, 1ZS1B, 1ZS2B, 1ZS3B		
	1ZS06, 1ZS16, 1ZS26, 1ZS36 1ZS0C, 1ZS1C, 1ZS2C, 1ZS3C		
2012 QX56	1ZS0C, 1ZS1C, 1ZS2C, 1ZS3C 1ZS0D, 1ZS1D, 1ZS2D, 1ZS3D		
	1ZS0E, 1ZS1E, 1ZS2E, 1ZS3E		
	1YN0A, 1YN1A, 1YN2A, 1YN3A		

7. Follow the on-screen instructions to navigate C-III plus and reprogram the ECM.

NOTE:

- In some cases, more than one new P/N for reprogramming is available.
 - ▶ In this case, the screen in Figure 3 displays.
 - Select and use the reprogramming option that <u>does not</u> have the message "Caution! Use ONLY with ITBXX-XXX".
- If you get this screen and it is <u>blank</u> (no reprogramming listed), it means there is no reprogramming available for this vehicle. Close C-III plus and refer back to ASIST for further diagnosis.

CONSULT-III plus Ver.	VIN:	Vehicle :	Country : U.S.A.
Back Prin	nt Screen Capture Mode	Recorded Help 11.80	
Re/programming, Configuration	Precaution		firm Vehicle
Select Program Data			
		elow. firm the vehicle selection, VIN and	
System	ENGINE		
Current Part Number	Part Number After Re	pro/programming Other Inf	formation
xxxxxx-xxxxxxx	XXXXXXX-XXXXXXX	xxxxxxxxxxxxxxx	000000000
XXXXXX-XXXXXXX	XXXXXXX-XXXXXXX	000000000000000000000000000000000000000	0000000000
		0/0	Next

Figure 3

8. When the screen in Figure 4 displays, reprogramming is complete.

NOTE: If the screen in Figure 4 does <u>not</u> display (reprogramming does <u>not</u> complete), refer to the information on page 9.

- 9. Disconnect the battery charger from the vehicle.
- 10. Select Next.




Figure 4

NOTE:

- In the next steps, starting on page 10, you will perform Throttle Valve Closed Position, Idle Air Volume Learn, Accelerator Closed Position, and DTC erase.
- These operations are required before C-III plus will provide the final reprogramming confirmation report.

Do not disconnect plus VI or shut down CONSULT III plus if reprogramming does not complete.

If reprogramming does <u>not</u> complete and the "!?" icon displays as shown in Figure 5:

- Check battery voltage (12.0–15.5 V).
- Ignition is ON, engine OFF.
- External Bluetooth[®] devices are OFF.
- All electrical loads are OFF.
- Select <u>retry</u> and follow the on screen instructions.
- <u>"Retry" may not go through on first</u> <u>attempt and can be selected more</u> <u>than once</u>.

CONSULT-II plus Ver	VN	Vaticle	Country : Japan
Back Hone Print Screen	Scheme Mode	sortbed Data	12.3V VI MI
sonigiation	Transfer Data	Confirm Resul	1313
Confirm Result			
Reprogramming or programming is no operation on this ECU. Touch "Retry" to retry reprogramming		t you can retry reprogriph	
Part number after Reproc/programming		284B2-XXXXX	
		284B2-XXXXX	
Part number before Reprog/programming		284B2-XXXXX	
		284B2-XXXXX QASHQAI	
Reprog/programming			00
Reprog/programming Vehicle		QASHQAI	00
Reprog/programming Vehicle VIN		QASHQAI SJNFDNJ10U1000	
Reprog/programming Vehicle VIN System		QASHQAI SJNFDNJ10U1000 BCM	

Figure 5

If reprogramming does <u>not</u> complete and the "X" icon displays as shown in Figure 6:

- Check battery voltage (12.0 15.5 V).
- CONSULT A/C adapter is plugged in.
- Ignition is ON, engine OFF.
- Transmission is in Park.
- All C-III plus / VI cables are securely connected.
- All C-III plus updates are installed.
- Select <u>Home</u>, and restart the reprogram procedure from the beginning.

CONSULT-ILDUS Wr	VIN Vehicle : QASHQAI	County : Japan
Bark Hone Print Screek	Hele Restricted Hele 9.7V	💭 💥 🖿 🛄 🔀
Redprograming.	Transfer Eata	9/9
Confirm Result		
with procedure.	rly. DNSULT version, IGW/Power switch position, shift positi /lonce, and start the reprogramming again.	on and etc
Part number after Reprog/programming	284E2-XXXXX	
Current part number	284E2-XXXXX	
Vehicle	QASHQAI	
VIN	SJNFDNJ10U100000	
VIN System	SUNFDNJ10U100000 BCM	
System	всм	

Figure 6

- 11. Follow the on-screen instructions to perform the following:
 - Throttle Valve Closed Position
 - Idle Air Volume Learn (IAVL)

NOTE:

- > Listed below are common conditions required for IAVL to complete.
- > If IAVL does not complete within a few minutes, a condition may be out of range.
- Refer to the appropriate Electronic Service Manual (ESM) for specific conditions required for the vehicle you are working on.
 - Engine coolant temperature: 70 -105° C (158 221°F)
 - o Battery voltage: More than 12.9V (At idle)
 - o Selector lever: P or N
 - Electric load switch: OFF (Air conditioner, headlamp, rear window defogger)
 - o Steering wheel: Neutral (Straight-ahead position)
 - o Vehicle speed: Stopped
 - o Transmission: Warmed up
- Accelerator Pedal Close Position Learning
- Erase DTCs

Continue to the next page.

- 12. When the entire reprogramming process is complete, the screen in Figure 7 will display.
- 13. Verify the before and after part numbers are different.
- 14. Print a copy of this screen (Figure 7) and attach it to the repair order for warranty documentation.
- 15. Select Confirm.

CONSULT-III plus Ver VIN:	Vehicle :	Country : U.S.A.			
Back Home Print Screen Capture	Measurement Mode Recorded Data Parts 14.	3V VI MI ■ □			
Re/programming, Configuration	se All DTCs Print Result / Operation Complete	18/18			
Print Result / Operation Complete					
All tasks are completed. Confirm LAN access, touch "Print" to print out this page. In case CONSULT can NOT immediately access to LAN or printer, Screen Capture function is available for temporally storage of this page. Touch "Screen Capture", and save it. Screen capture data is in "CIII plus Data Folder" on desk top, and open the folder named "ScreenImages".					
	ер 23710				
Part number before Reprog/programming	3 23710				
Vehicle	*****				
VIN	*****				
System	ENGINE	Step Print			
Date	11/3/201× 2:10:21 AM				
	1/1	Step 15 Confirm			

Figure 7

16. Close C-III plus.

- 17. Turn the ignition OFF.
- 18. Disconnect the plus VI from the vehicle.
- 19. Test drive the vehicle and make sure it operates correctly and the MIL is OFF.
 - If the MIL comes ON, go back to ASIST for further diagnostic information.
 - Diagnosis and repairs beyond ECM reprogramming are not covered by this bulletin.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Reprogram Engine Control Module	(1)	DE97AA	ZE	32	(2) (3)

(1) Reference the Repair Order and use the <u>current</u> ECM P/N written down in step 6 of the **SERVICE PROCEDURE** as the PFP.

(2) Reference the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

(3) FRT allows adequate time to access DTC codes and reprogram ECM. No other diagnostic procedures subsequently required. Do NOT claim any Diagnostic Op Codes with this claim.