



Mitsubishi Motors North America, Inc.  
**PARTS BULLETIN**

<b>SUBJECT:</b>  <b>SRS CONNECTOR CORROSION –          SAFETY RECALL CAMPAIGN</b>	No: 54-MG-01-16
	Date: FEBRUARY 2016
	Model: 2014 - 15 Mirage

**PURPOSE:**

If a driver enters the vehicle with his/her shoes covered with snow containing road salt, the carpet may become soaked when the snow melts. If the carpet becomes soaked in the area of the driver's foot rest, water containing road salt may contaminate a wiring connector terminal located in a junction box behind the kick panel to the left of the driver's foot rest. If this occurs, the connector terminal may corrode over time and cause several warning lamps to illuminate, including the SRS warning lamp.

If the SRS warning lamp is illuminated and the vehicle is subsequently involved in a collision requiring frontal air bag deployment, the timing of the frontal airbag deployment may be delayed.

Please reference **SAFETY RECALL BULLETIN SR-16-001** for the procedures on how to remedy the above occurrence as well as to prevent potential future corrosion.

**AFFECTED VEHICLES:**

Certain 2014 - 15 Mirage vehicles built between July 27, 2013 and September 2, 2015.

**IMPORTANT**

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or non-compliance is remedied.

**PARTS INFORMATION:** Reference SR-16-001 Safety Recall Campaign Steps.

Applicability	DESCRIPTION	Part Number	Quantity
Discolored and corrosion present	Full Service Kit	MW400198	1
-OR-			
Not discolored or corroded	Sheet, PVC	8558B820	1

**PARTS ORDERING AND ALLOCATION INFORMATION:**

There will be two (2) forced allocation shipments by MMNA Sales to your dealership. They will be processed via the 'R' order type and will be shipped immediately upon order creation.

The First Forced allocation will be P/n 8558B820 Sheet, PVC. The quantities shipped to your dealership will repair all affected vehicles currently in dealer stock.

The Second forced allocation will be both P/n 8558b820 (Sheet, PVC) and P/n MW400198 (Full Service Kit) to cover the initial expected customer demand.



# Mitsubishi Motors North America, Inc. PARTS BULLETIN

SUBJECT: <b>SRS CONNECTOR CORROSION – SAFETY RECALL CAMPAIGN</b>	No: 54-MG-01-16
	Date: FEBRUARY 2016
	Model: 2014 - 15 Mirage

## PARTS ORDERING AND ALLOCATION INFORMATION, continued:

The Timing of the forced allocation quantities will be as follows:

**1<sup>st</sup> allocation** of only P/n **8558B820** (Sheet, PVC), to repair affected on ground stock, will begin *arriving* at your dealership on Tuesday February 2, 2016.

**2<sup>nd</sup> allocation** of both P/n **8558B820** (Sheet, PVC) and P/n **MW400198** (Full Service Kit) will begin *shipping* to your dealership on Thursday February 4, 2016.

Additional orders may be placed via the MDL as necessary.

**Carefully** review the procedure steps in **Safety Recall bulletin SR-16-001** to insure you are ordering the correct part for the correct remediation step.

Each VIN will either require a Full Service Kit (P/n MW400198) **or** the single PVC sheet (P/n 8558B820) for remediation. **DO NOT** order both to fix one (1) vehicle.

- Discolored, rusted, or corroded connectors and terminals, the VIN requires P/n **MW400198** Full Service Kit.  
Note: Only a few kits are anticipated to be needed, order sparingly.
- If the connectors and terminals are **NOT** discolored, **NOT** rusted, or **NOT** corroded the VIN requires P/n **8558B820** Sheet, PVC.  
Note: It is anticipated this part will be needed for the majority of the fixes.

Contact your local Zone Representative, District Parts and Service Manager, or Facing PDC for questions or comments.

