

## Creaking and squeaking noises heard from instrument panel, caused by front axle suspension strut

---

|                   |                                                                                                |
|-------------------|------------------------------------------------------------------------------------------------|
| Topic number      | LI32.25-P-063651                                                                               |
| Version           | 5                                                                                              |
| Design group      | 32.25 Shock absorbers/damper struts/spring struts                                              |
| Date              | 08-26-2016                                                                                     |
| Validity          | MODEL 205, 253, 213 without CODE 489                                                           |
| Reason for change | Note included on avoiding the removal of the shock absorber, as per information from Australia |
| Reason for block  |                                                                                                |

---

### Complaint:

Creaking or squeaking from the area of the front axle on rough roads, heard in the area of the instrument panel.

Also audible while stationary when the suspension is deflected.

| Attachments            |                                       |
|------------------------|---------------------------------------|
| File                   | Description                           |
| 1_Geräusch_Knarzen.mp3 | Noise recording of creaking/squeaking |

### Cause:

1. When the suspension strut is compressed heavily, the expansion of the stop buffer may allow the boot to come into contact with the casing of the head bearing.
2. Squeaking noises between the buffer and the piston rod.
3. Squeaking noises due to micromovements between the upper coil of the spring and the upper spring cup mounting.

| Attachments            |                                                |
|------------------------|------------------------------------------------|
| File                   | Description                                    |
| 1_Geräusch Knarzen.JPG | Cause and remedy (lubrication area for grease) |

### Remedy:

Note: It is not necessary to remove the shock absorber. The work for eliminating the noise can be performed in the installed state.

1. Raise vehicle at front axle.
2. Pull down stop buffer with boot.
3. Apply Krytox fluid/ grease to the following locations (also refer to picture in attachment):
  - Area (1) is the contact surface between the spring and the spring cup mounting.
  - Area (2) is the contact surface between the dust boot and the strut tower.

# XENTRY TIPS

4. Grease with special grease A 001 989 84 51 between shock absorber piston rod and stop buffer.

5. Push stop buffer with boot back up to original position.

6. Lower vehicle.

Note: If the problem persists after greasing, create a PTSS case with the following information!

- Photo of labels on suspension strut/shock absorber, see attachment: "Photo of suspension strut label no. 1" and "Photo of suspension strut label no. 2".
- Photo on which the areas covered in grease can be seen in greater detail.

| Attachments               |                                                                 |
|---------------------------|-----------------------------------------------------------------|
| File                      | Description                                                     |
| Fetten Anschlagpuffer.jpg | Greasing with A0019898451 09 between piston rod and stop buffer |
| Fettstellen.jpg           | Areas to be greased                                             |

| Symptoms                                                   |
|------------------------------------------------------------|
| Chassis/suspension / Noises / Grunting                     |
| Chassis/suspension / Noises / Howling/whistling/squeaking  |
| Chassis/suspension / Axle / Front axle / Noises / Grunting |
| Chassis/suspension / Axle / Front axle / Noises / Squeals  |
| Body / Interior equipment / Instrument panel / Noise       |
| Chassis/suspension / Noises / Creaks                       |

| Parts           |     |     |                |          |                                                                                      |     |
|-----------------|-----|-----|----------------|----------|--------------------------------------------------------------------------------------|-----|
| Part number     | ES1 | ES2 | Designation    | Quantity | Note                                                                                 | EPC |
| A 000 989 36 60 |     |     | Lubricant      | 1        | Krytox fluid                                                                         | X   |
| A 000 989 38 60 |     |     | Lubricant      | 1        | Krytox grease                                                                        | X   |
| A 001 989 84 51 | 09  |     | Special grease | 1        | Special grease 400 g, for greasing between stop buffer and shock absorber piston rod | X   |

| Attachments               |                                       |
|---------------------------|---------------------------------------|
| File                      | Description                           |
| Label_1_Federbein_205.JPG | Photo of suspension strut label no. 1 |
| Label_2_Federbein_205.JPG | Photo of suspension strut label no. 2 |

| Operation numbers/damage codes |                                                                                          |      |             |      |
|--------------------------------|------------------------------------------------------------------------------------------|------|-------------|------|
| Op. no.                        | Operation text                                                                           | Time | Damage code | Note |
| 32-1938                        | LUBRICATE STOP BUFFER WITH BOOT FOR SUSPENSION STRUT OF 1ST VEHICLE AXLE, LOCATION:..... | 2 AW | 32322 36    |      |

# XENTRY TIPS

| Validity          |        |              |
|-------------------|--------|--------------|
| Vehicle           | Engine | Transmission |
| C (205)           | *      | *            |
| C (205) - 205.002 | *      | *            |
| C (205) - 205.003 | *      | *            |
| C (205) - 205.004 | *      | *            |
| C (205) - 205.008 | *      | *            |
| C (205) - 205.009 | *      | *            |
| C (205) - 205.012 | *      | *            |
| C (205) - 205.036 | *      | *            |
| C (205) - 205.037 | *      | *            |
| C (205) - 205.040 | *      | *            |
| C (205) - 205.042 | *      | *            |
| C (205) - 205.045 | *      | *            |
| C (205) - 205.049 | *      | *            |
| C (205) - 205.066 | *      | *            |
| C (205) - 205.086 | *      | *            |
| C (205) - 205.087 | *      | *            |
| C (205) - 205.140 | *      | *            |
| C (205) - 205.142 | *      | *            |
| C (205) - 205.145 | *      | *            |
| C (205) - 205.204 | *      | *            |
| C (205) - 205.208 | *      | *            |
| C (205) - 205.209 | *      | *            |
| C (205) - 205.212 | *      | *            |
| C (205) - 205.236 | *      | *            |
| C (205) - 205.237 | *      | *            |
| C (205) - 205.240 | *      | *            |
| C (205) - 205.242 | *      | *            |
| C (205) - 205.245 | *      | *            |
| C (205) - 205.266 | *      | *            |
| C (205) - 205.286 | *      | *            |
| C (205) - 205.287 | *      | *            |
| C (205) - 205.386 | *      | *            |
| C (205) - 205.387 | *      | *            |
| E (213)           | *      | *            |
| GLC (253)         | *      | *            |