



**NUMBER:** 18-027-16

**GROUP:** Vehicle Performance

**DATE:** March 30, 2016

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 18-072-15, DATED OCTOBER 14, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE ADDITIONAL DTCS, SYSTEM IMPROVEMENTS, NOTE IN REPAIR PROCEDURE AND LABOR OPS.**

**FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.**

**THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.**

***SUBJECT:***

Flash: 6.7L Diagnostic And System Improvements

***OVERVIEW:***

This bulletin involves reprogramming the Engine Control Module/Powertrain Control Module (ECM/PCM) with the latest available software.

***MODELS:***

2016	(DJ)	Ram 2500 Pickup
2016	(D2)	Ram 3500 Pickup

**NOTE: This bulletin applies to vehicles within the following markets/countries:  
NAFTA.**

**NOTE: This bulletin applies to vehicles built on or before March 28, 2016 (MDH 0328XX) equipped with a 6.7L Cummins Diesel engine (Sales Code ETK).**

**SYMPTOM/CONDITION:**

\*\*These DTCs have been changed from a one trip fault to a two trip fault:

- P2280 - Air Flow Restriction / Leak Between Air Cleaner And MAF
- P203C - (Diesel Exhaust Fluid) Reductant Level Sensor Circuit Low
- P208D - (Diesel Exhaust Fluid) Reductant Pump Control Circuit High\*\*

A small number of customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation a technician may find the following Diagnostic Trouble Codes (DTCs) set in the PCM memory:

- \*\*P2281 - Air Leak Between MAF and Throttle Body.
- P218F - Reductant No Flow Detected.
- P0218 - Transmission High Temperature Operation Activated (68RFE Only).
- P0868 - Line Pressure Low, MIL Action (68RFE Only).\*\*
- U110E - Lost Ambient Temperature Message.
- P205E - (Diesel Exhaust Fluid) Reductant Tank Temperature Sensor Circuit Intermittent (setting when the block heater is plugged in).

In addition to addressing the above DTCs, the following powertrain system improvements/enhancements are also included in this software release:

- \*\*68RFE Transmission Overall Shift Quality Improvements.
- Test results fix for partial range misfire (68RFE).
- Ambient Air Temperature Improvements.
- Stationary Desoot with wiTECH Fix.\*\*
- OBD Misfire Monitoring Improvement (68RFE Only).

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptoms/conditions listed above or if the technician finds the DTCs, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

**NOTE: \*\*If DTC U1601 is present, the ECM P/N did not update or the engine did not start after the flash, then the flash may have been unsuccessful. Restart the flash update.\*\***

1. Reprogram the ECM/PCM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the "HELP" tab on the upper portion of the wiTECH window, then "HELP CONTENTS." This will open the Welcome to wiTECH Help screen where help topics can be selected.

2. Is this vehicle equipped with the 68RFE automatic transmission?
  - a. Yes>>> Proceed to [Step #3](#).
  - b. No>>> Turn ignition key "OFF" for 75 seconds then proceed to [Step #5](#).
3. Turn ignition key "OFF" for 10 minutes and proceed to [Step #4](#).
4. Perform the transmission "Quicklearn" procedure. Follow the detailed service procedures available in DealerCONNECT/TechCONNECT, Service Info Section 08 - Electrical > 8E - Electronic Control Modules > MODULE, Transmission Control > Standard Procedure > Quicklearn. Proceed to [Step #5](#).
5. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allows them to be cleared. Proceed to [Step #6](#).
6. Perform the PCM Configuration routine in wiTECH located in the PCM "Misc. Functions" menu tab.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
**18-19-04-ET	Module, Engine Control/Powertrain Control (ECM/PCM) (Manual Trans/Aisin)-Reprogram (1 - Semi-Skilled)	10 - DIESEL	0.4 Hrs.
18-19-04-EU	Module, Engine Control/Powertrain Control (ECM/PCM) 68RFE Trans Only - Reprogram (1 - Semi-Skilled)	10 - DIESEL	0.6 Hrs.**

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 14 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

***FAILURE CODE:***

**The dealer must choose which failure code to use. If the customer came in with an issue and the dealer found updated software to correct that issue, use failure code CC, for all other use failure code RF.**

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash