



NUMBER: 08-004-16

GROUP: Electrical

DATE: January 22, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-004. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Two Underhood Relays Not Capped and Unsecured

OVERVIEW:

This bulletin involves inspecting the wiring harness and if needed, attaching relays to secure the harness.

MODELS:

2016 (JK) Jeep Wrangler

NOTE: This bulletin applies to vehicles within the following markets/countries: LATAM and APAC.

NOTE: This bulletin applies to vehicles built on or after September 30, 2015 (MDH 0930XX) and on or before October 05, 2015 (MDH 1005XX) equipped with the 2.8L I4 Turbo Diesel Engine (Sales Codes ENS).

SYMPTOM/CONDITION:

The customer may describe a buzz, squeak or rattle (BSR), coming from the engine compartment.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
2 (AR)	56055667AB	Relay
2 (AR)	06506132AA	Push Pin M7.0X20.0

NOTE: Push pins can only be ordered in multiples of 12.

REPAIR PROCEDURE:

1. Open the Hood and locate the ECM (Engine Control Module). Look for loose wiring connectors to the right of the ECM. Does the vehicle have two wire connectors not connected?




Fig. 1 Inspect Engine Wiring Harness

1- Loose Wire Harness

-
- a. YES>>> Continue with the Repair Procedure [Step #2](#).
 - b. NO>>> This bulletin has been completed, use LOP (08-65-68-90) to close the active RRT.
2. Install the relays to the loose wiring connectors ([Fig. 2](#)).




Fig. 2 Connect Relays to Loose Wiring Connector

1 - Attach relays to the loose connectors.

3. Attach the relay to the component tray with PIA push pins as shown ([Fig. 3](#)).



Fig. 3 Fasten Relays to Component Tray

1 - Fasten relays to tray.

POLICY:
Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-65-68-90	Inspect Engine Wiring Harness and/or Install 2 Relays (2 - Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------