

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2006-2016	All	All	All	All

## Condition

40 16 01 February 2, 2016 2043146

### Strut or Shock Absorber Leak Assessment

Customer states one or more of the shocks/struts appear to have an oil leak.

## **Technical Background**

Oil residue on the piston rod or shock/strut body may be normal, see Service for further details.

## **Production Solution**

Information only.

### Service

#### Information for assessing whether a shock/strut has a leak or not:

- Only inspect shock/strut when vehicle is clean and dry.
- Ensure no other leaks are present in the area that may lead to misdiagnosis.



#### Leaking Shock Absorber:

• An oil residue that runs down the shock/strut body may indicate a leak (see figure 1 and 2).



Figure 1) shock/strut Leak



Figure 2) shock/strut leak

#### © 2016 Volkswagen Group of America, Inc.

Page 2 of 4



#### Shock/Strut with Minor Oil Film:

• A slightly dried oil residue at the top of the shock/strut does not indicate a leak (see figure 3 and 4).

This type of residue can be caused by shock/strut assembly and sweating around the seal.



Figure 3) Not a leaking shock/strut



Figure 4) Not a leaking shock/strut

© 2016 Volkswagen Group of America, Inc.

Page 3 of 4



### Warranty

Information only.

## **Required Parts and Tools**

Information only.

## **Additional Information**

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2016 Volkswagen Group of America, Inc.

Page 4 of 4