



Service Bulletin

File in Section: -
 Bulletin No.: 16-NA-015
 Date: January, 2016

TECHNICAL

Subject: Engine Stall or Stumble - Replace Coil Connector

Attention: Vehicles equipped with 1.4L RPO LUJ/LUV turbocharged engine.


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze	2011	2014			LUJ/LUV	All

Condition	Some customers may comment that the engine stalls, stumbles, and/or has a hesitation when accelerating from a stop.
Cause	The ignition coil connector may have fretting on the terminals, causing a poor connection.

Correction

Inspect the 7-pin coil pack connector for poor terminal contact or fretting. Replace connector with part number 19300958 if needed.

Service Procedure



2191363

Ignition coil (1) and 7-pin ignition coil wiring harness connector (2)

1. Inspect the 7-pin coil pack connector (2) for damage. If no damage is found, follow normal SI diagnostics.
2. If damage is found, replace the coil pack connector. Refer to *Ignition Coil Replacement* and *Splicing Copper Wire Using Splice Sleeves* in SI.
3. Verify the repair.

Parts Information

Description	Part Number	Qty
CONNECTOR KIT (W/ LEADS)	19300958	1

Warranty Information

Labor Operation	Description	Labor Time
5430880	Connector with Leads Assembly Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION