

## Service Bulletin

File in Section:

Bulletin No.: 16-NA-003

Date: February, 2016

# **TECHNICAL**

**Subject:** Chirp, Squeak Noise from Rear of Vehicle

Attention: This Bulletin also applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2016	Start of 2016 Production	December 15, 2015	All	All
Chevrolet	Corvette	2014	2016	Start of 2014 Production	November 16, 2015		
Cadillac	ATS - V Series	2016	2016	Start of 2016 Production	December 3, 2015		
Cadillac	CTS - V Series	2016	2016	Start of 2016 Production	December 2, 2015		

Condition	Some customers may comment on hearing a squeak or chirp noise coming from the rear of the vehicle. The noise may be reported as being intermittent.		
Cause	The noise may be caused by the opening/closing of the exhaust values during normal performance.		
Additional Option RPOs	Chevrolet – Equipped with LGX Engine / NPP Exhaust, LT1 Engine / N10 or NPP Exhaust, or LT4 Exhaust Cadillac – Equipped with LF4 or LT4 Engine		

#### Correction

**Note:** There is a normal, audible noise associated with the opening/closing of the exhaust valves. The squeak/ chirp noise noting the condition is an additional, more shrill noise, and may be intermittent, influenced by temperature and humidity.

Confirm that the front or rear/tail pipe valves are the cause of the condition by activating the flow control function of the exhaust system.

- 1. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle in SI.
- Use GDS to verify the exhaust flow control valves open and close when commanding the Exhaust Flow Control Valve On and Off, with a scan tool.
- 3. For Camaro and Corvette models, the engine sound management setting must be set to "Auto" to enable the scan tool to operate the valves.

**Note:** The noise may only occur during valve opening OR closing of a valve, not always both.

- Command the flow control functioning numerous times and listen for any squeak/chirp noise, over and above the normal activation noise.
- 5. If the squeak/chirp noise is evident, continue ahead to the lubrication service procedure below.

#### **Service Procedure**




4340714

**Important:** Regardless the noisy valve location, lubricate ALL exhaust valves on the system.

Generously lubricate the forward, and rear if equipped, exhaust valves following the steps below:

1. Fully raise the vehicle.




4340724

Position a drop cloth below the valve being lubricated.



4340727

 Apply DRY SLIDE Multi-Purpose Dry Lubricant, P/N 1052948 (in Canada, use 89021511), into the valve by inserting the nozzle into the slot on the valve. Liberally apply a generous amount of the lubricant.



4340730

- Move the drop cloth to and repeat application at both, or all four valve locations, depending on the exhaust system.
- 5. With all valves lubricated, command the flow control functioning numerous times on all valves, to work the lubricant into the valve.
- 6. During the flow control functioning, also verify the squeak/chirp noise has been eliminated.

#### **Parts Information**

Description	Part Number	Qty
LUBRICANT, DRI-SLIDE, 4 OZ AEROSOL VOC COMPLIANT	01052948 P/N 89021511	1
LUBRICANT, DRI-SLIDE, 149 G (Canada)	(Canada)	

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4081088*	Apply Lubricant to Exhaust Valves	0.4 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	2
	January 22, 2016 — Added Corvette breakpoint, updated Additional Option RPOs, updated step #2 and added step #3 to Correction.