

## Service Bulletin

Bulletin No.: 16-NA-141 Date: May, 2016

# TECHNICAL

#### Subject: Audible Noise Inside Car While Accelerating During a Right Hand Turn

Γ	Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
			from	to	from	to		
	Cadillac	CT6	2016	2016			LGW, LGX	

Involved Region or Country	NORTH AMERICA		
Condition	Some customers may comment that a noise is heard inside the vehicle while accelerating during a right hand turn.		
Cause	This may be caused by the exhaust pipe and/or pipe heat shield contacting the underbody heat shield.		

### Correction

If the noise concern was found coming from the exhaust pipe and/or the heat shield, the exhaust system needs to be re-positioned for proper clearance.

### **Service Procedure**



- 1. Raise the vehicle.
- 2. Inspect the clearance between the driver side down pipe heat shield and the underbody exhaust heat shield.
- 3. Loosen the driver side exhaust clamp bolts (1), passenger side exhaust flange nuts (2) and the catalytic converter bracket nuts (3).
- 4. Re-position the exhaust system for better clearance and re-torque the system. Refer to SI for proper torque specifications.

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time			
4081228*	Exhaust System Re- Alignment	0.5 hr			
*This is a unique Labor Operation for Bulletin use only.					

4500487		
Version	1	
Modified		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION