
			GROUP		NUMBER	
Q	SO HYUI		TIES. CA	MPAIGN	16-01-036	
Technical Service Bulletin		DATE		MODEL(S)		
	recinical		AUG	UST 2016	ELANTRA (ADa)	
SUE	BJECT: OU	OUTSIDE DOOR HANDLE FASTENER TORQUE ADJUSTMENT (SERVICE CAMPAIGN TNN)				
		-				
* IMPORTANT		*** Dealer Stock and	*** Dealer Stock and Retail Vehicles ***			

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the service department, access Hyundai Motor America's "warranty vehicle information" screen via WEBDCS to identify open campaigns.

Description: Certain 2017 Elantra (ADa) may have lower than specified torque on the fastener securing the outside door handle(s). This may lead to improper operation of the outside door handle(s).

This bulletin describes the procedure to check and tighten the outside door handle cap screws as required.





Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

Wear protective goggles and gloves when performing the procedures in this bulletin.

WARRANTY INFORMATION:

Op. Code	Operation	Op. Time
60CA08R1	Check and Tighten O/S Handle Base (4EA)	0.2 M/H

NOTE: Submit Claim on Campaign Claim Entry Screen.

SERVICE PROCEDURE:

The procedures below are described for the driver side door. Procedure for passenger side and rear doors are same as the driver side.

1. Open the driver door and remove the black cover to access the door handle base screw using a trim tool.

Use No-Mar trim tool to prevent damage to paint.



SUBJECT: OUTSIDE DOOR HANDLE FASTENER TORQUE ADJUSTMENT (SERVICE CAMPAIGN TNN)

2. Use torque tool to check the torque and tighten screw as necessary.

Tightening torque: 7.8Nm – 10.8Nm (0.8 ~ 1.1 kgf.m, 5.8 ~ 7.9 lb-ft)

Note: Click wrench or Digital torque wrench can be used.

Set wrench to within spec limit **8.9 Nm** (**0.9kgf.m, 6.6 lb-ft**) recommended. Tighten screw as needed. In some instances, tightening may not be required.

Do not overtighten screw. This can damage outside handle cap and may require replacement. This will not be covered under warranty.

3. Reinstall black screw cover.

