

# Technical Service Bulletin



## 20 MIL on (DTC P310B - Low fuel pressure regulation / pressure out of specification)

20 16 71 2043758/2 June 15, 2016. Supersedes Technical Service Bulletin Group 20 number 16-66 dated April 12, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 Cabriolet, A6, A7, Q5	2012 - 2016	All	2.0L and 3.0L engine

## Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (Added customer codes)
1	4/12/2016	Initial publication

- MIL on.
- Customer has problems starting the car.
- The issue usually occurs when the temperature outside is around 120°F or higher, after start-stop journeys with longer idle speed phases and hot engine.
- **DTC P310B** (Low fuel pressure control, fuel pressure outside tolerance) stored in the engine control module (ECM), J623 (address word 01) with one of the following symptom codes:
  - Symptom code 6183 for 3.0 TFSI.
  - Symptom code 2636 and/or 2637 for 2.0 TFSI.
- Intake air temperature is usually above 140°F (60°C) in the freeze frame data of the diagnostic log.

## Technical Background

Vapors in fuel system.

## Production Solution

Not applicable.

# Technical Service Bulletin



## Service

Check the low fuel pressure, the fuel delivery rate, and the fuel lines according to ELSA specifications. If there are deviations, replace the fuel delivery unit. If no fault is found, delete the event memory and do not replace the fuel delivery unit.

## Warranty

<b>Claim Type:</b>	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
<b>Service Number:</b>	2066		
<b>Damage Code:</b>	0040		
<b>Labor Operations:</b>	<b>For A4, A5, A5 cab, and Q5:</b>		
	Electric fuel pump remove+reinstall	2066 1900	130 TU
	<b>For A6 and A7:</b>		
	Electric fuel pump remove+reinstall	2066 1950	20 TU
	Fuel drain+fill	2003 1700	110 TU
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on diagnostic protocol (Max 30 TU)
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
<b>Claim Comment:</b>	As per TSB #2043758/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2043758) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.