



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-159

Date: June, 2016

TECHNICAL

Subject: Squeak and/or Rubbing Noise from Steering Column Area

Brand:	Model:	Model Year:		Breakpoint:	Engine:	Transmission:
		from	to			
Chevrolet	Colorado	2015	2016	Vehicles Built Prior to April 25, 2016		
GMC	Canyon	2015	2016			

Involved Region or Country	North America
Condition	Some customers may comment on a squeak and/or rubbing noise coming from the steering column area.
Cause	This condition may be due to the inner and/or outer intermediate steering shaft boots (seals) being out of position.

Correction



4512167



4381042

Inspect the intermediate steering shaft inner and outer boots (seal) for being out of position as shown above. If the boots are out of position, use a flat trim stick to properly seat the boots.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
7480218*	Inspecting and/or Re-Adjusting Both (Inner and Outer) Intermediate Steering Shafts Boots	0.5 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	2
Modified	June 13, 2016 – Added breakpoint

