

Service Bulletin

File in Section:

Bulletin No.: 16-NA-262

Date: August, 2016

TECHNICAL

Subject: Night Vision Inoperative, Service Night Vision System is Displayed

	Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
ı			from	to	from	to		
l	Cadillac	CT6	2016	2016				

Involved Region or Country	North America and N.A. Export Regions		
Additional RPO	UV3		
Condition	Some customers may comment on the following conditions: Night vision does not work. Service Night Vision System is displayed.		
Cause	This may be caused by the night vision video cable not connected to the back of the Instrument Panel Cluster (IPC).		

Correction

Verify no DTCs are logged into the night vision module. If you see a DTC, then follow proper service procedure for that DTC. If no DTCs are logged, then you will need to check the cable connection at the back of the cluster.

Service Procedure

- 1. Remove the IPC. Refer to *Instrument Cluster Replacement* in SI.
- Verify the night vision connector is firmly inserted into the back of the IPC.
- 3. Install the IPC and check for proper operation.

If the night vision video cable is found to be securely attached, then further investigation of the cluster may be required.

Warranty Information

Labor Operation	Description	Labor Time	
3480378*	Night Vision Cable to IPC Inspection and Connection	2.1 hrs	
*This is a unique Labor Operation for Bulletin use only.			

Version	1
Modified	