



Service Bulletin

INFORMATION

Subject: Front Sunroof Sunshade Will Not Latch or is Difficult to Latch in the Closed Position

Models: 2010-2017 Buick Enclave
2010-2017 Chevrolet Traverse
2010-2016 GMC Acadia
2017 GMC Acadia Limited
2010 Saturn OUTLOOK
Equipped with Sunroof RPO C3U
and Built After August 1, 2009

Attention: This PI also applies to any of the above models that may be Export from North America vehicles.

This PI has been revised to add the 2015-2017 Model Years. Please discard PI0341D.

Condition/Concern #1

Some customers may comment that the front sunroof sunshade will not latch in the closed position.
The molded-in sunroof sunshade striker on the sunroof module may be broken.

Recommendation/Instructions #1

Replace the front sunroof sunshade striker with the service replacement striker by riveting it to the sunroof module assembly.



1. Check that the sunroof sunshade striker fits into where the broken striker was by placing the sunroof sunshade striker under the bottom of the front rail. File to fit if necessary.
2. Place the sunroof sunshade striker on the top surface of the front rail to locate the holes. Mark the hole locations.



Important: When drilling holes, be careful not to drill through the headliner.

3. Drill two 4.5 mm holes.
4. Place the sunroof sunshade striker on the bottom surface of the front rail and align the holes.



5. Install rivets from the top side to secure the sunroof sunshade striker in place.
6. Verify striker operation.

Condition/Concern #2

Some customers may comment that the front sunroof sunshade is difficult to latch in the closed position.

The front rail of the sunroof module may sag due to high ambient temperatures causing the sunshade striker to sit lower. This is more prevalent on dark colored vehicles when parked in direct sunlight for an extended period of time.

Recommendation/Instructions #2

Remove the existing molded-in sunroof sunshade striker and install the service replacement striker by riveting it to the sunroof module assembly.



Important: When removing the striker, be careful not to cut/damage the headliner.

1. Remove the existing sunshade striker using a Dremel or similar tool.
2. Place the sunroof sunshade striker on the top surface of the front rail to locate the holes. Mark the hole locations.

Important: When drilling holes, be careful not to drill through the headliner.

3. Drill two 4.5 mm holes.
4. Place the sunroof sunshade striker on the top surface of the front rail and align the holes.



5. Install rivets from the bottom side to secure the sunroof sunshade striker in place.
6. Verify striker operation.

Parts Information

Part Number	Description	Qty
Kent Automotive Part # 1980 or Equivalent	4 mm (5/32 inch) Aluminum Blind Rivet with Grip Range between 1.19–6.35 mm (3/64–1/4 inch)	2
22791456*	Sunroof Sunshade Striker	1

*Due to a limited supply of this part, please DO NOT order for dealer stock.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
6080008*	Sunroof Sunshade Striker Replacement	0.3 hr
*This is a unique Labor Operation for Bulletin use only.		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION