September 10, 2016

03585 Version 4

Audio Unit Software Update

HONDA

Supersedes 16-022, dated June 3, 2016, to revise the information highlighted in yellow

AFFECTED VEHICLES

Year	Model	Trim	VIN Range	
2016	Civic	2-Door EX 1.5L	2HGFC3GH	thru 2HGFC3G
2016	Civic	2-Door Touring 1.5L	2HGFC3GH	thru 2HGFC3GH
2016	Civic	4-Door EX 1.5L	19XFC1GE	thru 19XFC1GE
2016	Civic	4-Door EX 1.5L	2HGFC1GH	thru 2HGFC1GH
2016	Civic	4-Door EX 2.0L	19XFC2GE	thru 19XFC2GE
2016	Civic	4-Door EX 2.0L	2HGFC2GH	thru 2HGFC2GH
2016	Civic	4-Door Touring 1.5L	19XFC1GE	thru 19XFC1GE
2016	Civic	4-Door Touring 1.5L	2HGFC1GH	thru 2HGFC1GH

REVISION SUMMARY

- Added FACTORY DATA RESET procedures.
- Added a symptom under BACKGROUND.
- Updated software information in REPAIR PROCEDURE.

BACKGROUND

There is a problem with the audio unit software, which may lead to one or more of the following symptoms:

- *Bluetooth*[®] Audio skips.
- Audio icon does not work.
- GPS error code 1302 sets.
- Error message SXM check tuner appears.
- GPS initialization screen appears.
- Rear camera is stuck on in Park.
- There are pairing problems with *Bluetooth*[®] HandsFreeLink[®](HFL).
- GPS shows inaccurate vehicle location.

- Rear camera does not display.
- There is no sound from Apple CarPlay[™] after connecting *Bluetooth*[®], then USB.
- System does not recognize "SXM" in voice commands.
- Pandora[®] does not play after HFL call ends.
- Voice commands do not work.
- Android Auto[™] will not play.

CORRECTIVE ACTION

Update audio unit software using the audio-navigation system USB update device.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation	Description	Flat Rate	Defect	Symptom	Template	Failed Part
Number		Time	Code	Code	ID	Number
0100A1	Update the audio unit software.	0.3 hr	03214	03217	16-022A	39101-TBA-A21

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.


REQUIRED TOOLS

Tool Name	Part Number
Audio-Navigation System Update Device (USB Drive)	07AAZ-TBAA100



REPAIR PROCEDURE

- 1. Park the vehicle outside in a well ventilated area or attach to a appropriate exhaust vent.
- 2. Start the engine and leave it running throughout the entire software update process.
- 3. On the **HOME** screen, press and hold the **MENU** icon, **Audio** icon, and Day/Night button at the same time for 3 seconds.
- 4. Select Detail Information & Setting.



5. Select Version.

	Return	
Monitor Check	B-CAN	
Unit Check	F-CAN	
Audio Check	Version	
Guideline Setup	Vehicle status	
Functional Setup	GPS Information	

6. Scroll to Software Loader and check the version.

• Check the software version loaded, then go to the applicable update procedure:

Software Version	Page number		HUL G2P Engine 20.8.0
1.F182.87	<mark>3</mark>		HUL TTS Engine1.0.2
1.F183.52	3		VehicleDbManager1.0
<mark>1.F184.60</mark>	<mark>3</mark>		veniciebbManageri.u
1.F186.67	<mark>5</mark>	-	com.mitsubishielectric.ada.util.vehiclerw4.2.2-15 3
		DBOOT	1.9_20160318023038
		Software loader	1.F186.67
		System µCom	H62F00 70.E2.12

7. After checking the version, select **Return** three times to return to the **HOME** screen.

Software Update Procedure for Software Loader 1.F186.67

- 1. Connect the USB update device once the audio unit has booted up and the HOME screen appears.
- 2. Once the USB device is inserted, a pop-up screen appears with the current and new software versions displayed. (This may take a minute or two) Select **Yes.**

NOTE:

- Once you start the update, you do not have to stay with the vehicle.
- If a pop-up screen does not appear, check the version numbers. If the vehicle is not updated, then do the FACTORY DATA RESET PROCEDURE.

AUDI	0 SOURCE	A,			7:19
	Audio		C d	Phone	~
	Wou	ld you like	e to update	?	
		Ver. 1. Ver. 1.			
	Yes			No	

The main software update screen will appear and the update is copied from the USB device.



Once the update is copied, the audio unit reboots automatically.



3. You may get a GPS check pop-up, if you do, follow the instructions to acquire the GPS signal. NOTE: If you cannot acquire the GPS signal, remove the USB device and go to step 4.

> The system lost power and is acquiring its location from the GPS satellites. This usually takes less than 10 minutes. * Start the engine. * Park the vehicle in an open area away from trees, power lines, and tall buildings. * Remove loose articles, mobile phones, or electrical accessories located near the GPS antenna. * If this screen is displayed repeatedly when starting the vehicle, see your dealer.

4. Once the HOME screen reappears, remove the USB device and go to SOFTWARE UPDATE CONFIRMATION.



Software Update Procedure for Software Loader 1.F182.87/1F183.52/1.F184.60

- 1. Connect the USB update device once the audio unit has booted up and the **HOME** screen appears.
- Once the USB device is inserted, a pop-up screen appears with the current and new software versions displayed. (This may take a minute or two) Select Yes.

NOTE:

- Once you start the update, you do not have to stay with the vehicle.
- If a pop-up screen does not appear, check the version numbers. If the vehicle is not updated then do the FACTORY DATA RESET PROCEDURE.



The main software update screen appears and the update is copied from the USB device.

Current	Ver.	XXXXXX	
New	Ver.	XXXXXXX	
ao			33%
Please do	Copying not turn o	g off the veh USB devic	icle

Once the update is copied, the audio unit reboots automatically.



The system software update screen appears and the software should finish downloading.



Once the update is complete, the audio unit reboots automatically a second time.



- 3. The **Anti Theft System** screen appears. Push and hold the Audio icon for more than 2 seconds to enable the system.
 - NOTE: If nothing is done for 30 seconds the screen goes black. Select the Day/Night button or BACK icon to return to the screen.



4. You may get a GPS check pop-up. If you do, follow the instructions to acquire the GPS signal. NOTE: If you cannot acquire the GPS signal, remove the USB device and go to the next step.

> The system lost power and is acquiring its location from the GPS satellites. This usually takes less than 10 minutes. * Start the engine. * Park the vehicle in an open area away from trees, power lines, and tall buildings. * Remove loose articles, mobile phones, or electrical accessories located near the GPS antenna. * If this screen is displayed repeatedly when starting the vehicle, see your dealer.


5. Once the HOME screen reappears, remove the USB device and go to SOFTWARE UPDATE CONFIRMATION.



SOFTWARE UPDATE CONFIRMATION

- 1. On the **HOME** screen, press and hold the MENU icon, Audio icon, and Day/Night button at the same time for 3 seconds.
- 2. Select Detail Information & Setting.

3. Select Version.



	Return	
Monitor Check	B-CAN	
Unit Check	F-CAN	
Audio Check	Version	
Guideline Setup	Vehicle status	
Functional Setup	GPS Information	

4. Scroll to **Software loader** and **System μCom** and check the versions. The software should be updated to the following versions:


	Return	
1	HUL G2P Engine 20.8.0	
	HUL TTS Engine1.0.2	
	VehicleDbManager1.0	
	com.mitsubishielectric.ada.util.vehiclerw4.2.2-15 4	
DBOOT	1.9_20160329042950	
Software loader	1.F186.69	
System µCom	H61F00.70.E2.12	

- Software loader : 1.F186.69
- System μCom : H61F00 70.E2.12 (with XM radio function) H62F00 70.E2.12 (without XM radio function)
- 5. After verifying the software has been updated, select **Return** three times to return to the **HOME** screen. Go to DELETING ERROR HISTORY.



DELETING ERROR HISTORY


- 1. On the **HOME** screen, press and hold the MENU icon, Audio icon, and Day/Night button at the same time for seconds.
- 2. Select Detail Information & Setting.




3. Select Unit Check.

	Return
Monitor Check	B-CAN
Unit Check	F-CAN
Audio Check	Version
Guideline Setup	Vehicle status
Functional Setup	GPS Information

4. Select Error history.



5. Select Hard Error.



6. Select **Clear** on the bottom right.

			Return
		20150101 020309	
Date	20150101	20150101 015750	
Time	015035	20150101 015035	
Error code	1302	20150101 014715	
Simple description	GPS Receiver Error1	20150101 011815	
-		20150101 011458	
		Save	Clear

7. Select **Yes** on the **Confirmation** screen. The error history is now cleared, and the update complete.

				Return
Date	Confirmation			
Time	Deleted data cannot Continue?	be recovered.		
Formanda	Yes	No		
Error code				
Simple description	\wedge			
		Sav	Clear	

FACTORY DATA RESET PROCEDURE

NOTE:

- Have the service advisor inform the customer that the Factory Data Reset will remove any saved settings.
- Do the Factory Data Reset procedure only when directed to in the applicable software update procedure.
- Do the Factory Data Reset while the USB update device is connected.
- 1. Select **Settings** on the **HOME** screen.



2. Select System.




3. Scroll down and select Factory Data Reset.

😸 System Settings		3:19
All Home	Display	>
Volume Gestures	On	>
Change Skin		
Factory Data Reset		
Climate screen timeout	IV seconas	
Detail Information		¥
Default	OK	

4. Select **Next** on the pop-up screen.




5. Select **Yes** on the pop-up screen.



The system reset screen appears.

System Settings		3:21			
All Home	Display	>			
Volume Gestures	On				
Resetting the system to the original factory state					
Detail Information					
Default	OK				

6. Select OK.



7. An Android loading screen appears. After the loading has completed, go back to the applicable software update procedure.



END