

Quality Bulletin

TITLE:

Service Action S89808: Remove Sunroof Seal Model Year 2017 S90

GROUP: 83				CAR MARKET: United States and Canada		
REFERENCE BULLETINS: TJ 31993					ISSUE DATE: 2016-10-20	STATUS DATE: 2016-10-20
Service Personnel: Read and initial		SERVICE MANAGER	SERVICE WRITER	WARRANTY ADMINISTRATOR	Page	1 of 3

"Right first time in Time"

- A. SERVICE ACTION S89808 DESCRIPTION
- **B.** VEHICLES INVOLVED
- C. PARTS INFORMATION/PARTS RETURN
- D. OWNER NOTIFICATION
- E. VEHICLES IN RETAILER INVENTORY
- F. RETAILER RESPONSIBILITY
- G. REIMBURSEMENT PROCEDURES
- H. TECHNICIAN COMPETENCY REQUIREMENT
- I. RETAILER ALLOWANCE

A. SERVICE ACTION S89808 DESCRIPTION

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Campaign S89808 on certain model year 2017 S90 vehicles.

Volvo has identified that certain vehicles may have been incorrectly assembled with a rubber seal under the sunroof wind deflector. The rubber seal may become loose and wedged between the roof and sunroof.

The corrective action is to remove and discard the rubber seal and clean off residual adhesive.

Service Action S89808 affects 2,308 vehicles in the U.S. and 88 in Canada.

RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS ACTION.

Vehicles in retailer inventory must be upgraded prior to sale.

Quality Bulletin S89808



<u>PLEASE NOTE</u>: Service Action S89808 will be in effect until <u>December 31, 2018</u> regardless of mileage.

B. VEHICLES INVOLVED

NOTE: RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS SERVICE CAMPAIGN.

Vehicle eligibility must be confirmed:

• Inquire in VRC² - Vehicle Warranty where the message "Service Action S89808 Remove Sunroof Seal" will appear for eligible vehicles.

All vehicles should be checked for any incomplete recalls, service campaigns or service upgrades. All open Recall, Service Campaign or Service Action repairs should be completed.

C. PARTS INFORMATION / PARTS RETURN

No parts are required for this service action.

PARTS RETURN

No parts are required to be returned to TMA for this service action.

D. OWNER NOTIFICATION

No customer mailing is scheduled at this time.

E. VEHICLES IN RETAILER INVENTORY

Vehicles in retailer inventory must be completed prior to sale.

F. RETAILER RESPONSIBILITY

Retailers must check eligibility prior to completing this service action. All eligible vehicles must have this service action completed prior to customer delivery.

G. CAMPAIGN REIMBURSEMENT PROCEDURES

Service Action S89808 claims should be submitted using the LONG FORM application only.

H. TECHNICIAN COMPETENCY REQUIREMENT

The technician competency requirement for this repair is Level 1 Quality Tech.

Page 2 of 3 2016-10-20



Quality Bulletin S89808

I. RETAILER ALLOWANCE (LONG FORM APPLICATION)

Labor reimbursement is effective at time of release and may change in the future.

Claim Type: S89808

Cause Code: 02 CSC Code: XW Main OP: 99400

Operation NumberRepair DescriptionOtyLabor Time99400Remove Seal General Reimbursement10.1

2016-10-20 Page 3 of 3