

Service Bulletin

File in Section:

Bulletin No.: 16-NA-208

Date: June, 2016

TECHNICAL

Subject: A/C Intermittently Blows Warm and/or Insufficient Cooling

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Bianu.	woder.	from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2016	SOP	GF319551	LKN	All

Involved Region or Country	North America and Israel		
Additional Options (RPO)	Equipped with Electric Hybrid Propulsion 50 Kw Continuous Power (RPO HP4)		
Condition	Some customers may comment that their A/C intermittently blows warm or is not cooling enough. During diagnosis a technician may find DTC P2518 stored.		

Correction

If normal diagnostics lead to replacement of the B1C A/C Low Side Pressure Sensor, **DO NOT** replace the sensor at this time.

Update the K114B Hybrid Powertrain Control Module 2 software. Refer to *Hybrid Powertrain Control Module 2 Programming and Setup* in SI.

Note: After the vehicle has been reprogrammed, the outside air temperature (OAT) could default to 32° (0°C).

To relearn the OAT, the vehicle must be driven approximately above 32 km/h (20 mph) for 4 minutes. The OAT reading should then agree with the ambient temperatures.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810265	Hybrid Powertrain Control Module 2 Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	