

File in Section:

Bulletin No.: 16-NA-217

> Date: July, 2016

TECHNICAL

Minimum Startup Volume Too Loud Subject:

Attention: This Bulletin replaces PIC6196. Please discard PIC6196.

Brand:	d: Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.		from	to	from	to		
Buick	Cascada	2016	2016	SOP	June 22, 2016	All	All

Involved Region or Country	North America		
Additional Options (RPO)	Equipped with Radio AM/FM Stereo, Single CD, MP3 (RPO UHQ)		
Condition	Some customers may comment that the minimum default volume will not go below 19. As a result, customers who turn the vehicle/radio off with the volume level above 19 will experience high audio volume upon start up because it will only default to a minimum start up level of 19.		
Cause	This may be the result of a audio calibration concern.		

Correction

If you encounter a vehicle with the above concern, turn the radio to XM channel 0 so there is no audio.

Turn the volume all the way up to determine the highest level available. If the radio will go up to level 45, SPS reprogram the radio with the latest TIS2web calibrations, which are designed to address this concern. Refer to Radio Programming and Setup in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	