

Service Bulletin

File in Section:

Bulletin No.: 16-NA-218

Date: July, 2016

TECHNICAL

Subject: Brake Hydroboost Leaking Power Steering Fluid

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Бгапи:		from	to	from	to		
Chevrolet	Express	2010	2016			All	All
GMC	Savana	2010	2016			All	All

Involved Region or Country	North America, UAE, Israel		
Additional Options (RPO)	Equipped with Sales Package Ambulance (RPO YF2) or Shuttle Bus (RPO ANC)		
Condition	Some customers may comment on a power steering leak originating from the brake hydrobooster.		
Cause	This may be due to overheating (thermal set of the hydro boost seals) from lack of/insufficient cooling by the loop cooler.		

Correction

If you encounter a vehicle with the above concern, replace the power brake booster and the power steering cooler with a newly designed power steering cooler. Refer to Power Brake Booster Replacement and Power Steering Cooler Pipe/Hose Replacement in SI.

Important: When installing the newly designed power steering cooler, there is a fluid flow switch. This will not be connected to anything and will not interfere with the operation of the cooler.

Parts Information

Description	Part Number	Qty
BOOSTER ASM-P/B	84031702	1
COOLER ASM-P/S FLUID	25818863	1
NUT	11609746	2

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2480208*	Power Brake Booster and Fluid Cooler Inlet and Outlet Hose Replacement	1.6 hrs
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	