Audi

Technical Service Bulletin

01 MIL on (DTC P2181, P0597, or P0599 Cooling system performance)

19 16 71 2038045/3 June 23, 2016. Supersedes Technical Service Bulletin Group 01 number 15-22 dated May 13, 2015 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
S6, S7, RS 7, S8, A8	2013 - 2015	All	4.0TFSI

Condition

REVISION HISTORY				
Revision	Date	Purpose		
3	-	Revised header data (Added model years; added DTCs) Revised Condition (Added DTCs)		
		Revised Service (Completely revised) Revised Warranty (Updated labor operations)		
2	5/13/2015	Revised Required Parts and Tools (Corrected part number and updated quantity)		
1	8/15/14	Initial publication		

- MIL on.
- One or more of the following DTCs is stored in the engine control module (ECM), J623 (address word 01):
 - DTC P218100 (Cooling System Performance)
 - DTC P059700 (Thermostat heater control circuit open)
 - DTC P059900 (Thermostat heater control circuit high)

Technical Background

DTC P218100 will be stored if, after a specified air flow (warm-up phase), the measured engine temperature does not reach the value in the timing map. Particles in the cooling system from the production process affect the closing of the coolant thermostat.



Replacing the coolant temperature sender does not fix the problem.

Audi

Technical Service Bulletin

Production Solution

Optimized coolant thermostat.

Service

- 1. Replace the coolant thermostat F265 with part number 079121115BD.
- 2. Fill the new coolant additive in the cooling system according to manufacturer guidelines. Observe the mixture ratio and filling-up procedure.



Only mix distilled water with coolant additives. Distilled water provides optimum corrosion protection.



The filling procedure outlined in Elsa must be followed. It is important that the vacuum-down, filling, and bleeding processes for the specific vehicle being repaired are used.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.			
Service Number:	1958			
Damage Code:	0016			
	Thermostat remove + reinstall (S6, S7, S8, A8)	1958 1921	220 TU	
	Thermostat remove + reinstall (RS 7)	1958 1923	250 TU	
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	0150 0000	10 TU	
	Road test prior to service procedure	No allowance	0 TU	
	Road test after service procedure	0121 0004	10 TU	
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DAI	DP allowance de	tails)	
Claim Comment:	As per TSB # 2038045/3			

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Part Number	Part Description	Quantity
079121115BD	Map controlled engine cooling thermostat F265	1
G 013A8J1G	Coolant additive	1
Outside material	Distilled water (obtain locally)	As needed (Max \$10.00)

Tool Number	Tool Description
VAS 6096	Cooling System Charge Unit
VAG 1974/8	Adapter
VAG 1978/10	Adapter
VAS 6208	Drip tray
T10007A	Refractometer

Additional Information

All parts and service references provided in this TSB (2038045) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.