

© 2016 Mazda Motor of America, Inc.

Subject: REAR CONSOLE LID DOES NOT LATCH CLOSE (BROKEN LATCH)	Bulletin No: 09-047/16
	Last Issued: 08/11/2016

BULLETIN NOTE

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted below in Red beside the change bars.

Previously Issued TSBs:	Date(s) Issued
09-012/15	04/17/15


APPLICABLE MODEL(S)/VINS

2014-2015 Mazda3 (Japan built) vehicles with VINS lower than JM1BM*****227327 (produced before August 1, 2014)

2014-2015 Mazda3 (Mexico built) vehicles with VINS lower than 3MZBM*****157427 (produced before October 6, 2014)

DESCRIPTION

Some vehicles may exhibit the rear console lid (A) that does not latch close due to a broken latch (B). The latch may be broken by excessive external force applied to the lid. To eliminate the concern, the shape of the rear console lid latch has been changed to increase the strength.




Customers having this concern should have their vehicle repaired using the following repair procedure.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by „Áudo-it-yourselfers.„Áü Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the console upper lid (A) with a modified latch (B) according to the instructions on MS3 online (CONSOLE LID REMOVAL/INSTALLATION).

NOTE: The console upper lid has been established as a new service part.



3. Verify repair.

PART(S) INFORMATION

Part Number	Description	Qty.	Notes
BHN1-64-140A	Console Lid, Upper	1	BHN1-64-450C-02, PVC
BHN2-64-140A	Console Lid, Upper	1	BHN2-64-450D-02, Vinyl Leather
BJS7-64-140	Console Lid, Upper	1	BJS7-64-450A-02, PVC

NOTE: Check the part number of the console upper lid for the subject VIN using the GPEC, then use the corresponding console lid inner.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty.
- Additional diagnostic time cannot be claimed for this repair.
- This TSB can be performed by D329 Mazda Certified Lube Technicians.

Warranty Type	A
Symptom Code	42
Damage Code	9A
Part Number Main Cause	****-64-140*
Quantity	1
Operation Number / Labor Hours:	XXM3PXRX / 0.2 Hrs.
TSB can be performed by D329 Mazda Certified Lube Technicians:	Yes